



Before usage



After opening



The observed performance reduction is mainly caused by high CPU utilization, supported by increased memory consumption and additional I/O activity.

Aim

To compare the performance of two computers using processor specification.

specification	computer 1	computer 2
CPU Model	Intel i5	Intel i7
Base speed	2.40 GHz	2.60 GHz
Turbo speed	4.20 GHz	4.70 GHz
Cores	4	12
Logical Processors	8	16

Conclusion :- Computer 2 is expected to provide better overall performance because it has more cores, more logical processors, and a higher turbo frequency.

3. Aim :

To analyse how the 8085 microprocessor executes instruction by observing the program counter (PC), Accumulator and Flag register during execution.

Program

MVI A, 05H

ADI 03H

STA 8000H

HLT

Execution cycle

1. Fetch: The Program counter contains the address of the instruction
* The PC is automatically incremented to the next instruction
2. Decode: The control unit decodes the fetched instruction
3. Execute: The Arithmetic Logic Unit performs the addition

Final result:

Initial Accumulator = 05H

Value Added = 03H

Final Accumulator = 08H

Memory Location 8000H = 08H

