



# **Aviation Investigation Final Report**

Location: Watkins, Colorado Accident Number: CEN23LA253

Date & Time: June 10, 2023, 12:15 Local Registration: N6886P

Aircraft: Piper PA-24-250 Aircraft Damage: Substantial

**Defining Event:** Landing gear not configured **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

#### **Analysis**

The pilot reported that shortly before touchdown he noticed the landing gear selector still in the up position. The pilot moved the selector to the down position, but the landing gear were unable to fully extend before touchdown. The bottom of the fuselage was substantially damage during the wheels-up landing. The pilot reported that there were no preaccident mechanical malfunctions or failures with the airplane that would have precluded normal operation.

Additionally, the pilot reported he did not use a prelanding checklist to ensure that the landing was extended before touchdown.

#### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to extend the landing gear before landing. Contributing to the accident was the pilot's failure to utilize the prelanding checklist to ensure the landing gear was extended before landing.

### **Findings**

Personnel issues Use of equip/system - Pilot

Personnel issues Forgotten action/omission - Pilot

Personnel issues Use of checklist - Pilot

Page 2 of 5 CEN23LA253

### **Factual Information**

### **History of Flight**

Landing-flare/touchdown Landing gear not configured (Defining event)
--

#### **Pilot Information**

Certificate:	Private	Age:	78,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Lap only
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	BasicMed Without waivers/limitations	Last FAA Medical Exam:	June 27, 2022
Occupational Pilot:	No	Last Flight Review or Equivalent:	January 13, 2023
Flight Time:	704 hours (Total, all aircraft), 122 hours (Total, this make and model), 510 hours (Pilot In Command, all aircraft), 4.6 hours (Last 90 days, all aircraft)		

#### **Aircraft and Owner/Operator Information**

Aircraft Make:	Piper	Registration:	N6886P
Model/Series:	PA-24-250	Aircraft Category:	Airplane
Year of Manufacture:	1960	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	24-2022
Landing Gear Type:	Retractable - Tricycle	Seats:	4
Date/Type of Last Inspection:	June 1, 2023 Annual	Certified Max Gross Wt.:	3000 lbs
Time Since Last Inspection:	1 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	4510 Hrs at time of accident	Engine Manufacturer:	Lycoming
ELT:	Installed, not activated	Engine Model/Series:	O-540-A
Registered Owner:	On file	Rated Power:	250 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Page 3 of 5 CEN23LA253

### Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KCF0,5515 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	11:47 Local	Direction from Accident Site:	
<b>Lowest Cloud Condition:</b>	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	6 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	70°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.04 inches Hg	Temperature/Dew Point:	22°C / 9°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Watkins, CO (CFO)	Type of Flight Plan Filed:	None
Destination:	Watkins, CO	Type of Clearance:	VFR
Departure Time:	11:45 Local	Type of Airspace:	Class D

### **Airport Information**

Airport:	Colorado Air and Spaceport CFO	Runway Surface Type:	Asphalt
Airport Elevation:	5515 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	8	IFR Approach:	None
Runway Length/Width:	8002 ft / 100 ft	VFR Approach/Landing:	Full stop;Traffic pattern

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	39.793656,-104.54977(est)

Page 4 of 5 CEN23LA253

#### **Administrative Information**

Investigator In Charge (IIC):	Finne, Andrew
Additional Participating Persons:	Joshua Friederichs; FAA-FSDO; Denver, CO
Original Publish Date:	August 31, 2023
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=192424

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 CEN23LA253