



Aviation Investigation Final Report

Location: Norwood, Massachusetts Accident Number: ERA23LA364

Date & Time: September 6, 2023, 23:00 Local Registration: N400RW

Aircraft: Piper PA24 Aircraft Damage: Substantial

Defining Event: Collision with terr/obj (non-CFIT) **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The private pilot and passenger proceeded on the cross-country nigh flight and on arrival near the destination airport the pilot stated that he was instructed by air traffic control to descend through class B airspace on a straight-in approach to the runway, which required him to descend at a rate of about 1,000 ft-per-minute. While flying the straight-in approach he indicated that he was, "a little behind on the aircraft as we descended." With the lights and the runway in sight he descended too quickly on final approach and impacted airport approach lighting then the ground short of the runway, resulting in substantial damage to the right wing. The pilot stated that there were no preimpact mechanical malfunctions or failures of the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to fly an appropriate glide path during the landing approach, which resulted in a collision with approach lights and the ground short of the intended runway.

Findings

Personnel issues	Decision making/judgment - Pilot	
Aircraft	Descent/approach/glide path - Not attained/maintained	

Page 2 of 5 ERA23LA364

Factual Information

History of Flight

|--|

Pilot Information

Certificate:	Private	Age:	45,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	July 15, 2023
Occupational Pilot:	No	Last Flight Review or Equivalent:	February 5, 2023
Flight Time:	587 hours (Total, all aircraft), 39 hours (Total, this make and model), 70 hours (Last 90 days, all aircraft), 35 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Piper	Registration:	N400RW
	•	_	
Model/Series:	PA24 400	Aircraft Category:	Airplane
Year of Manufacture:	1964	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	26-63
Landing Gear Type:	Retractable - Tricycle	Seats:	4
Date/Type of Last Inspection:	February 1, 2023 Annual	Certified Max Gross Wt.:	3600 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	3871 Hrs as of last inspection	Engine Manufacturer:	Lycoming
ELT:	Installed, not activated	Engine Model/Series:	IO-720-A1A
Registered Owner:	On file	Rated Power:	400 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None
Time Since Last Inspection: Airframe Total Time: ELT: Registered Owner:	Installed, not activated On file	Engine Manufacturer: Engine Model/Series: Rated Power: Operating Certificate(s)	Lycoming IO-720-A1A 400 Horsepower

Page 3 of 5 ERA23LA364

Meteorological Information and Flight Plan

Visual (VMC)	Condition of Light:	Night
KOWD,49 ft msl	Distance from Accident Site:	0.43 Nautical Miles
22:53 Local	Direction from Accident Site:	350°
Clear	Visibility	8 miles
	Visibility (RVR):	
/	Turbulence Type Forecast/Actual:	Unknown / None
	Turbulence Severity Forecast/Actual:	N/A / N/A
29.76 inches Hg	Temperature/Dew Point:	23°C / 21°C
No Obscuration; No Precipitation		
Nantucket, MA (ACK)	Type of Flight Plan Filed:	None
Norwood, MA	Type of Clearance:	VFR flight following
22:30 Local	Type of Airspace:	
	KOWD,49 ft msl 22:53 Local Clear / 29.76 inches Hg No Obscuration; No Precipitate Nantucket, MA (ACK) Norwood, MA	KOWD,49 ft msl Distance from Accident Site: 22:53 Local Direction from Accident Site: Clear Visibility Visibility (RVR): / Turbulence Type Forecast/Actual: Turbulence Severity Forecast/Actual: 29.76 inches Hg Temperature/Dew Point: No Obscuration; No Precipitation Nantucket, MA (ACK) Type of Flight Plan Filed: Norwood, MA Type of Clearance:

Airport Information

Airport:	Norwood Memorial Airport OWD	Runway Surface Type:	Asphalt
Airport Elevation:	49 ft msl	Runway Surface Condition:	Dry
Runway Used:	35	IFR Approach:	None
Runway Length/Width:	4007 ft / 100 ft	VFR Approach/Landing:	Full stop;Straight-in

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	42.18348,-71.171337(est)

Page 4 of 5 ERA23LA364

Administrative Information

Investigator In Charge (IIC):	Monville, Timothy
Additional Participating Persons:	Philip D. Kingston; FAA/FSDO; Boston, MA
Original Publish Date:	December 13, 2023
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=193025

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 ERA23LA364