



Aviation Investigation Final Report

Location: Smyrna, Tennessee Accident Number: ERA24LA106

Date & Time: February 5, 2024, 23:28 UTC Registration: N2150G

Aircraft: Cessna 172 Aircraft Damage: Substantial

Defining Event: Birdstrike **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Instructional

Analysis

The flight instructor reported that during the initial climb, he observed a bird dive down from above the airplane. The bird impacted the top portion of the windshield, resulting in substantial damage to the windshield. After the impact, the pilots checked themselves for injuries and for any control issues with the airplane. Both pilots were uninjured, and the airplane operated normally. The flight instructor landed the airplane without further incident.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

An in-flight collision with a bird during initial climb.

Findings

Environmental issues Animal(s)/bird(s) - Ability to respond/compensate

Environmental issues Animal(s)/bird(s) - Effect on equipment

Factual Information

History of Flight

Initial climb Birdstrike (Defining event)

Pilot Information

Certificate:	Commercial	Age:	39,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	None	Restraint Used:	Unknown
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 1 With waivers/limitations	Last FAA Medical Exam:	September 26, 2023
Occupational Pilot:	No	Last Flight Review or Equivalent:	November 30, 2023
Flight Time:	262 hours (Total, all aircraft), 256 hours (Total, this make and model), 202 hours (Pilot In Command, all aircraft), 23 hours (Last 90 days, all aircraft), 4 hours (Last 30 days, all aircraft), 0 hours (Last 24 hours, all aircraft)		

Flight instructor Information

Certificate:	Commercial; Flight instructor	Age:	29,Female
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Unknown
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine; Instrument airplane	Toxicology Performed:	
Medical Certification:	Class 1 With waivers/limitations	Last FAA Medical Exam:	January 19, 2023
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	January 8, 2024
Flight Time:	1226 hours (Total, all aircraft), 1060 hours (Total, this make and model), 1140 hours (Pilot In Command, all aircraft), 156 hours (Last 90 days, all aircraft), 52 hours (Last 30 days, all aircraft), 0 hours (Last 24 hours, all aircraft)		

Page 2 of 5 ERA24LA106

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N2150G
Model/Series:	172 S	Aircraft Category:	Airplane
Year of Manufacture:	2003	Amateur Built:	
Airworthiness Certificate:	Normal; Utility	Serial Number:	172S9516
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	January 8, 2024 100 hour	Certified Max Gross Wt.:	2550 lbs
Time Since Last Inspection:	50 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	12352.8 Hrs at time of accident	Engine Manufacturer:	Lycoming
ELT:	Installed, not activated	Engine Model/Series:	IO-360-L2A
Registered Owner:	MSB AVIATION LLC	Rated Power:	180 Horsepower
Operator:	MSB AVIATION LLC	Operating Certificate(s) Held:	Pilot school (141)

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	MQY,543 ft msl	Distance from Accident Site:	25 Nautical Miles
Observation Time:	17:56 Local	Direction from Accident Site:	271°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	9 knots /	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	350°	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	29.94 inches Hg	Temperature/Dew Point:	12°C / 0°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Lebanon, TN (M56)	Type of Flight Plan Filed:	None
Destination:	Smyrna, TN (MQY)	Type of Clearance:	None
Departure Time:	16:00 Local	Type of Airspace:	Class E

Page 3 of 5 ERA24LA106

Airport Information

Airport:	SMYRNA MQY	Runway Surface Type:	
Airport Elevation:	543 ft msl	Runway Surface Condition:	Unknown
Runway Used:		IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	36.008167,-86.518186(est)

Page 4 of 5 ERA24LA106

Administrative Information

Investigator In Charge (IIC):	Gibson, Kurt
Additional Participating Persons:	Joseph Patterson; FAA/FSDO; Nashville, TN
Original Publish Date:	April 12, 2024
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=193751

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 ERA24LA106