



# **Aviation Investigation Final Report**

Location: Alta, Iowa Accident Number: CEN23LA336

Date & Time: July 29, 2023, 07:30 Local Registration: N402PR

Aircraft: AIR TRACTOR INC AT-402B Aircraft Damage: Substantial

**Defining Event:** Collision with terr/obj (non-CFIT) **Injuries:** 1 None

Flight Conducted Under: Part 137: Agricultural

#### **Analysis**

The pilot reported that he was completing an aerial application flight over a cultivated field. During the fourth pass, the airplane encountered a dust devil (also called a whirlwind), lost lift and impacted powerlines. Upon impact with the powerlines the rudder separated from the airplane and the airplane began a left turn. Unable to arrest the turn, the pilot reduced power and made a forced landing to the field that he was spraying. Upon touch down the left main landing gear separated from the fuselage and the airplane slid to a stop.

The airplane sustained substantial damage to the left wing, vertical stabilizer and rudder. The operator reported there were no preimpact mechanical malfunctions or failures with the airframe or the engine that would have precluded normal operation.

A review of the Federal Aviation Administration Aviation (FAA) Weather Handbook (FAA-H-8083-28) and the FAA Aeronautical Information Manual found no detailed information listed about dust devils or the potential hazards of flying through dust devils.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The airplane's encounter with a dust devil, which resulted in a loss of lift, and subsequent collision with powerlines.

#### **Findings**

Aircraft Altitude - Attain/maintain not possible

Personnel issues Aircraft control - Pilot

**Environmental issues** Dust devil/whirlwind - Ability to respond/compensate

**Environmental issues** Dust devil/whirlwind - Effect on equipment

Environmental issues Dust devil/whirlwind - Contributed to outcome

Page 2 of 6 CEN23LA336

## **Factual Information**

### **History of Flight**

Maneuvering-low-alt flying	Other weather encounter
Maneuvering-low-alt flying	Collision with terr/obj (non-CFIT) (Defining event)
Landing	Off-field or emergency landing

#### **Pilot Information**

Certificate:	Commercial; Flight instructor; Private	Age:	52,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Center
Other Aircraft Rating(s):	Glider	Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane single-engine	Toxicology Performed:	
Medical Certification:	Class 2 Waiver time limited special	Last FAA Medical Exam:	December 21, 2022
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	October 24, 2022
Flight Time:	6600 hours (Total, all aircraft), 1500 hours (Total, this make and model), 6550 hours (Pilot In Command, all aircraft), 60 hours (Last 90 days, all aircraft), 40 hours (Last 30 days, all aircraft), 8 hours (Last 24 hours, all aircraft)		

Page 3 of 6 CEN23LA336

### **Aircraft and Owner/Operator Information**

Aircraft Make:	AIR TRACTOR INC	Registration:	N402PR
Model/Series:	AT-402B	Aircraft Category:	Airplane
Year of Manufacture:	2013	Amateur Built:	
Airworthiness Certificate:	Restricted (Special)	Serial Number:	402B-1282
Landing Gear Type:	Tailwheel	Seats:	1
Date/Type of Last Inspection:	June 15, 2023 Annual	Certified Max Gross Wt.:	7000 lbs
Time Since Last Inspection:		Engines:	1 Turbo prop
Airframe Total Time:	1679 Hrs as of last inspection	Engine Manufacturer:	Pratt & Whitney Canada
ELT:	Not installed	Engine Model/Series:	PT6A-15HE
Registered Owner:	BARTS FLYING SERVICE INC	Rated Power:	650 Horsepower
Operator:	BARTS FLYING SERVICE INC	Operating Certificate(s) Held:	Agricultural aircraft (137)
Operator Does Business As:	BARTS FLYING SERVICE INC	Operator Designator Code:	PFUG

### Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KSLB,1488 ft msl	Distance from Accident Site:	5 Nautical Miles
Observation Time:	07:35 Local	Direction from Accident Site:	149°
<b>Lowest Cloud Condition:</b>	Clear	Visibility	9 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	8 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	20°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.16 inches Hg	Temperature/Dew Point:	19°C / 18°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:		Type of Airspace:	Class G

Page 4 of 6 CEN23LA336

### **Wreckage and Impact Information**

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	42.675,-95.3042(est)

Page 5 of 6 CEN23LA336

#### **Administrative Information**

Investigator In Charge (IIC):	Brown, Zane
Additional Participating Persons:	Jason Glass; FAA FSDO; Des Moines, IA
Original Publish Date:	November 16, 2023
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=192749

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 CEN23LA336