



Aviation Investigation Final Report

Location: Matanuska Glacier, Alaska Accident Number: ANC23LA050

Date & Time: July 13, 2023, 15:30 Local Registration: N460JC

Aircraft: AVIAT AIRCRAFT INC A-1B Aircraft Damage: Substantial

Defining Event: Collision with terr/obj (non-CFIT) **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot reported he encountered downdrafts during landing on a remote gravel airstrip near a glacial base camp known for downdrafts and mountain rotors. He elected to depart the airstrip into rising terrain due to more favorable winds. During initial climb out the pilot reported the airplane encountered more downdrafts than expected. Unable to outclimb rising terrain, the pilot performed a forced landing in an area of rough, rock-covered terrain, and during landing the airplane sustained substantial damage to the wings and fuselage. The pilot reported that there were no pre-accident mechanical malfunctions or failures with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The airplane's encounter with downdrafts resulting in decreased performance insufficient to outclimb rising terrain.

Findings

Personnel issues	Flight planning/navigation - Pilot	
Personnel issues	Decision making/judgment - Pilot	
Aircraft	Climb rate - Not attained/maintained	
Environmental issues	Downdraft - Contributed to outcome	

Page 2 of 6 ANC23LA050

Factual Information

History of Flight

Initial climb	Collision with terr/obj (non-CFIT) (Defining event)
Initial climb	Off-field or emergency landing
Initial climb	Other weather encounter

Pilot Information

Certificate:	Airline transport; Flight instructor; Military	Age:	37,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	5-point
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine; Instrument airplane	Toxicology Performed:	
Medical Certification:	Class 1 Without waivers/limitations	Last FAA Medical Exam:	
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	10020 hours (Total, all aircraft), 898 hours (Total, this make and model), 3266 hours (Pilot In Command, all aircraft), 261 hours (Last 90 days, all aircraft), 44 hours (Last 30 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

Passenger Information

Certificate:		Age:	
Airplane Rating(s):		Seat Occupied:	Center
Other Aircraft Rating(s):		Restraint Used:	5-point
Instrument Rating(s):		Second Pilot Present:	Yes
Instructor Rating(s):		Toxicology Performed:	
Medical Certification:		Last FAA Medical Exam:	
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:			

Page 3 of 6 ANC23LA050

Aircraft and Owner/Operator Information

Aircraft Make:	AVIAT AIRCRAFT INC	Registration:	N460JC
Model/Series:	A-1B	Aircraft Category:	Airplane
Year of Manufacture:	2006	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	2343
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:		Certified Max Gross Wt.:	
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	Lycoming
ELT:	C126 installed, activated, aided in locating accident	Engine Model/Series:	0-360-A1P
Registered Owner:	On file	Rated Power:	180
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	PAAQ,233 ft msl	Distance from Accident Site:	46 Nautical Miles
Observation Time:	14:53 Local	Direction from Accident Site:	271°
Lowest Cloud Condition:	Few / 3500 ft AGL	Visibility	10 miles
Lowest Ceiling:		Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	110°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.1 inches Hg	Temperature/Dew Point:	23°C / 13°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Anchorage, AK (PAMR)	Type of Flight Plan Filed:	None
Destination:	Anchorage, AK (PAMR)	Type of Clearance:	None
Departure Time:	10:30 Local	Type of Airspace:	Class G

Page 4 of 6 ANC23LA050

Airport Information

Airport:	Scandinavian Peaks Hut Airstrip	Runway Surface Type:	
Airport Elevation:	5150 ft msl	Runway Surface Condition:	
Runway Used:		IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	61.589432,-147.47834(est)

Page 5 of 6 ANC23LA050

Administrative Information

Investigator In Charge (IIC):	Hill, Millicent
Additional Participating Persons:	Paula Huckleberry; Federal Aviation Administration (FAA); Wasilla, AK
Original Publish Date:	February 1, 2024
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=192639

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ANC23LA050