



# **Aviation Investigation Final Report**

Location: Santa Fe, New Mexico Accident Number: WPR23LA209

Date & Time: May 30, 2023, 14:05 Local Registration: N69PV

Aircraft: PIPISTREL DOO AJDOVSCINA VIRUS SW Aircraft Damage: Unknown

**Defining Event:** Hard landing **Injuries:** 1 Minor

Flight Conducted Under: Part 91: General aviation - Personal

### **Analysis**

The pilot reported that he experienced severe turbulence within about 10 miles of the airport as he was approaching to land. He further reported that during the landing, the airplane encountered a downdraft and bounced on touchdown. The airplane exited the runway to the left onto an adjacent grass area and nosed over, resulting in substantial damage to the right wing. The pilot reported there were no preaccident mechanical malfunctions or failures with the airplane that would have precluded normal operation during landing.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

An encounter with a downdraft during landing that resulted in a hard landing and the pilot's loss of control.

## **Findings**

Aircraft Landing flare - Capability exceeded

Personnel issues Aircraft control - Pilot

**Environmental issues** (general) - Effect on operation

Aircraft Descent rate - Attain/maintain not possible

Page 2 of 6 WPR23LA209

## **Factual Information**

### **History of Flight**

 Approach-VFR pattern final
 Other weather encounter

 Landing-flare/touchdown
 Hard landing (Defining event)

 Landing-landing roll
 Nose over/nose down

#### **Pilot Information**

Certificate:	Commercial; Flight instructor	Age:	76
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	Glider	Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	None	Last FAA Medical Exam:	
Occupational Pilot:	No	Last Flight Review or Equivalent:	July 15, 2022
Flight Time:	5600 hours (Total, all aircraft), 330 hours (Total, this make and model), 26 hours (Last 90 days, all aircraft), 11 hours (Last 30 days, all aircraft), 0 hours (Last 24 hours, all aircraft)		

Page 3 of 6 WPR23LA209

## **Aircraft and Owner/Operator Information**

PIPISTREL DOO AJDOVSCINA	Registration:	N69PV
VIRUS SW	Aircraft Category:	Airplane
	Amateur Built:	
Normal	Serial Number:	709 SWN 100
Tricycle	Seats:	2
May 9, 2023 Condition	Certified Max Gross Wt.:	1322 lbs
5 Hrs	Engines:	1 Reciprocating
210 Hrs at time of accident	Engine Manufacturer:	Rotax
Not installed	Engine Model/Series:	912ULS
On file	Rated Power:	100 Horsepower
On file	Operating Certificate(s) Held:	None
	VIRUS SW  Normal Tricycle May 9, 2023 Condition  5 Hrs 210 Hrs at time of accident Not installed On file	VIRUS SW  Aircraft Category:  Amateur Built:  Normal  Serial Number:  Tricycle  Seats:  May 9, 2023 Condition  Certified Max Gross Wt.:  5 Hrs  Engines:  210 Hrs at time of accident  Engine Manufacturer:  Not installed  Engine Model/Series:  On file  Operating Certificate(s)

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KSAF,6287 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	13:53 Local	Direction from Accident Site:	221°
<b>Lowest Cloud Condition:</b>	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	9 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	240°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.08 inches Hg	Temperature/Dew Point:	26°C / -6°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Moriarty, NM (0E0)	Type of Flight Plan Filed:	None
Destination:	Sante Fe, NM (KSAF)	Type of Clearance:	None
Departure Time:	15:00 Local	Type of Airspace:	Class D

Page 4 of 6 WPR23LA209

### **Airport Information**

Airport:	Santa Fe Municipal Airport SAF	Runway Surface Type:	Concrete
Airport Elevation:	6348 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	33	IFR Approach:	None
Runway Length/Width:	8366 ft / 150 ft	VFR Approach/Landing:	Full stop;Precautionary landing;Traffic pattern

## Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Unknown
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	35.617111,-106.08941(est)

Page 5 of 6 WPR23LA209

#### **Administrative Information**

Investigator In Charge (IIC):	Basti, Paymaun
Additional Participating Persons:	Vernon Rocket; FAA FSDO; Albuquerque, NM
Original Publish Date:	November 16, 2023
Last Revision Date:	June 20, 2024
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=192303

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 WPR23LA209