



Aviation Investigation Final Report

Location: Vernalis, California Accident Number: WPR23LA120

Date & Time: March 3, 2023, 12:30 Local Registration: N48492

Aircraft: GRUMMAN ACFT ENG COR-SCHWEIZER G-164B Aircraft Damage: Substantial

Defining Event: Low altitude operation/event **Injuries:** 1 Serious

Flight Conducted Under: Part 137: Agricultural

Analysis

The pilot reported he was spraying near power lines during an aerial application flight. He made several passes beneath a power line; however, during a subsequent pass, the pilot became distracted and struck the power line. The airplane impacted the ground and was destroyed by post-crash fire. The pilot reported no preaccident mechanical malfunctions or failures with the airplane that would have precluded normal operations.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain clearance from a power line during a low-level aerial application flight.

Findings

Personnel issues Monitoring environment - Pilot
Environmental issues Wire - Awareness of condition
Environmental issues Wire - Effect on equipment

Page 2 of 6 WPR23LA120

Factual Information

History of Flight

Maneuvering-low-alt flying	Low altitude operation/event (Defining event)
Maneuvering-low-alt flying	Collision with terr/obj (non-CFIT)

Pilot Information

Certificate:	Commercial; Flight instructor	Age:	60,
Airplane Rating(s):	Single-engine land	Seat Occupied:	Single
Other Aircraft Rating(s):	None	Restraint Used:	4-point
Instrument Rating(s):	Airplane	Second Pilot Present:	
Instructor Rating(s):	Airplane single-engine	Toxicology Performed:	
Medical Certification:	Class 2 Without waivers/limitations	Last FAA Medical Exam:	November 29, 2022
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	April 22, 2021
Flight Time:	17000 hours (Total, all aircraft), 16000 hours (Total, this make and model), 15000 hours (Pilot In Command, all aircraft), 50 hours (Last 90 days, all aircraft), 30 hours (Last 30 days, all aircraft), 5 hours (Last 24 hours, all aircraft)		

Page 3 of 6 WPR23LA120

Aircraft and Owner/Operator Information

Aircraft Make:	GRUMMAN ACFT ENG COR-	Registration:	N48492
	SCHWEIZER		
Model/Series:	G-164B	Aircraft Category:	Airplane
Year of Manufacture:	1976	Amateur Built:	
Airworthiness Certificate:	Restricted (Special)	Serial Number:	47B
Landing Gear Type:	Tailwheel	Seats:	1
Date/Type of Last Inspection:	Annual	Certified Max Gross Wt.:	5000 lbs
Time Since Last Inspection:	200 Hrs	Engines:	1 Turbo prop
Airframe Total Time:		Engine Manufacturer:	Pratt & Whitney
ELT:	Not installed	Engine Model/Series:	1340/an-1
Registered Owner:	D C APPLICATOR	Rated Power:	600
Operator:	On file	Operating Certificate(s) Held:	Agricultural aircraft (137)
Operator Does Business As:	D C AppliCATOR	Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KMOD,87 ft msl	Distance from Accident Site:	13 Nautical Miles
Observation Time:	12:53 Local	Direction from Accident Site:	92°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	9 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	270°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.01 inches Hg	Temperature/Dew Point:	13°C / 4°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Vernalis, CA (CA67)	Type of Flight Plan Filed:	None
Destination:	Vernalis, CA (CA67)	Type of Clearance:	None
Departure Time:	12:10 Local	Type of Airspace:	Class G

Page 4 of 6 WPR23LA120

Wreckage and Impact Information

Crew Injuries:	1 Serious	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	On-ground
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 Serious	Latitude, Longitude:	37.63118,-121.23477(est)

Page 5 of 6 WPR23LA120

Administrative Information

Investigator In Charge (IIC):	Basti, Paymaun
Additional Participating Persons:	David Lowther; Oakland FSDO; Oakland, CA
Original Publish Date:	June 23, 2023
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=106836

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 WPR23LA120