



Aviation Investigation Final Report

Location: Chesapeake, Virginia Accident Number: ERA24LA150

Date & Time: March 21, 2024, 14:10 Local Registration: N9269A

Aircraft: Cessna 170 Aircraft Damage: Substantial

Defining Event: Loss of control on ground **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The private pilot of the tailwheel-equipped airplane was returning to his home airport after refueling at a nearby airport. The pilot reported there was moderate turbulence while on final approach to land. Shortly after touchdown, the pilot reported that the left wing lifted and that he "did not correct fast enough and then overcorrected." The airplane ground looped, exited the runway, and the right main landing gear collapsed, resulting in the right wing and right elevator sustaining substantial damage. The pilot reported there were no preaccident mechanical malfunctions or failures that would have precluded normal operation of the airplane.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain directional control during landing, which resulted in a ground loop, runway excursion, and subsequent landing gear collapse.

Findings

Aircraft	Directional control - Not attained/maintained
Aircraft	Directional control - Not attained/maintained

Personnel issues Aircraft control - Pilot

Page 2 of 6 ERA24LA150

Factual Information

History of Flight

Landing-landing roll	Loss of control on ground (Defining event)
Landing-landing roll	Landing gear collapse

Pilot Information

Certificate:	Private	Age:	77,Male
Airplane Rating(s):	Single-engine land; Single-engine sea	Seat Occupied:	Left
Other Aircraft Rating(s):	Glider	Restraint Used:	3-point
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	October 5, 2022
Occupational Pilot:	No	Last Flight Review or Equivalent:	October 1, 2023
Flight Time:	2394 hours (Total, all aircraft), 80 hours (Total, this make and model), 2322 hours (Pilot In Command, all aircraft), 22 hours (Last 90 days, all aircraft), 9 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Page 3 of 6 ERA24LA150

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N9269A
Model/Series:	170 A	Aircraft Category:	Airplane
Year of Manufacture:	1949	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	19030
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	June 3, 2023 Annual	Certified Max Gross Wt.:	2200 lbs
Time Since Last Inspection:	71 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	3980 Hrs at time of accident	Engine Manufacturer:	Continental
ELT:	C91A installed, activated, did not aid in locating accident	Engine Model/Series:	C-145-2
Registered Owner:	On file	Rated Power:	145 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	PVG,23 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	13:56 Local	Direction from Accident Site:	25°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	3 knots /	Turbulence Type Forecast/Actual:	None / Terrain-Induced
Wind Direction:	340°	Turbulence Severity Forecast/Actual:	N/A / Light
Altimeter Setting:	30.23 inches Hg	Temperature/Dew Point:	11°C / -4°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Suffolk, VA (SFQ)	Type of Flight Plan Filed:	VFR
Destination:	Chesapeake, VA	Type of Clearance:	None
Departure Time:	13:55 Local	Type of Airspace:	Class G

Page 4 of 6 ERA24LA150

Airport Information

Airport:	HAMPTON ROADS EXEC PVG	Runway Surface Type:	Asphalt
Airport Elevation:	28 ft msl	Runway Surface Condition:	Dry
Runway Used:	10	IFR Approach:	None
Runway Length/Width:	5350 ft / 100 ft	VFR Approach/Landing:	Full stop;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	36.780765,-76.45128(est)

Page 5 of 6 ERA24LA150

Administrative Information

Investigator In Charge (IIC):	Gibson, Kurt
Additional Participating Persons:	Mark Jennings; FAA/FSDO; Richmond, VA
Original Publish Date:	May 29, 2024
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=193979

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ERA24LA150