

Aviation Investigation Final Report

Location: Trimble River Valley, Alaska Accident Number: ANC23LA086

Date & Time: September 24, 2023, 09:30 Local Registration: N2586R

Aircraft: Cessna 182K Aircraft Damage: Substantial

Defining Event: Collision with terr/obj (non-CFIT) **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot reported that he was landing at a remote off airport site. After touchdown, the left main landing gear contacted a large rock resulting in the left wheel separating from the main landing gear. Subsequently, the airplane veered left, nosed down, and both wings struck the ground resulting in substantial damage. The pilot reported that there were no pre-accident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's selection of unsuitable terrain for landing, which resulted in the left main landing gear (MLG) tire impacting a rock, resulting in the separation of the MLG wheel, and the subsequent loss of directional control.

Findings

Personnel issues Decision making/judgment - Pilot

Environmental issues (general) - Decision related to condition

Environmental issues Debris/dirt/foreign object - Effect on operation

Page 2 of 6 ANC23LA086

Factual Information

History of Flight

Landing-landing roll	Collision with terr/obj (non-CFIT) (Defining event)	
Landing-landing roll	Loss of control on ground	

Pilot Information

Certificate:	Airline transport; Flight engineer	Age:	50,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 1 With waivers/limitations	Last FAA Medical Exam:	August 22, 2023
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	April 21, 2023
Flight Time:	(Estimated) 18500 hours (Total, all aircraft), 400 hours (Total, this make and model), 13500 hours (Pilot In Command, all aircraft), 120 hours (Last 90 days, all aircraft), 45 hours (Last 30 days, all aircraft)		

Page 3 of 6 ANC23LA086

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N2586R
Model/Series:	182K	Aircraft Category:	Airplane
Year of Manufacture:	1967	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	18258286
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	Annual	Certified Max Gross Wt.:	2800 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	Continental
ELT:	C126 installed, activated, aided in locating accident	Engine Model/Series:	O-470R25
Registered Owner:	On file	Rated Power:	230 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Visual (VMC)	Condition of Light:	Day
PAWS,354 ft msl	Distance from Accident Site:	75 Nautical Miles
09:56 Local	Direction from Accident Site:	98°
Clear	Visibility	10 miles
None	Visibility (RVR):	
/	Turbulence Type Forecast/Actual:	/
	Turbulence Severity Forecast/Actual:	/
29.79 inches Hg	Temperature/Dew Point:	7°C / 3°C
No Obscuration; No Precipitation		
Lower Trimble River Valley, AK	Type of Flight Plan Filed:	None
Trimble River Valley, AK	Type of Clearance:	None
09:00 Local	Type of Airspace:	Class G
	PAWS,354 ft msl 09:56 Local Clear None / 29.79 inches Hg No Obscuration; No Precipitate Lower Trimble River Valley, AK Trimble River Valley, AK	PAWS,354 ft msl Distance from Accident Site: 09:56 Local Direction from Accident Site: Clear Visibility None Visibility (RVR): / Turbulence Type Forecast/Actual: Turbulence Severity Forecast/Actual: 29.79 inches Hg Temperature/Dew Point: No Obscuration; No Precipitation Lower Trimble River Valley, AK Type of Flight Plan Filed: AK Trimble River Valley, AK Type of Clearance:

Page 4 of 6 ANC23LA086

Airport Information

Airport:	Trimble River	Runway Surface Type:	Grass/turf;Gravel
Airport Elevation:	2500 ft msl	Runway Surface Condition:	Rough;Vegetation
Runway Used:	N/A	IFR Approach:	None
Runway Length/Width:	1200 ft / 50 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	61.77516,-152.15263

Page 5 of 6 ANC23LA086

Administrative Information

Investigator In Charge (IIC):	Rasmussen, Mitchell
Additional Participating Persons:	Robert Parsons ; FAA/FSDO; Anchorage, AK
Original Publish Date:	April 4, 2024
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=193153

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ANC23LA086