



Aviation Investigation Final Report

Location: Orland, California **Accident Number:** WPR23LA118

Date & Time: March 2, 2023, 15:00 Local Registration: N234SJ

Aircraft: Bell UH-1B Aircraft Damage: Substantial

Defining Event: Fuel exhaustion **Injuries:** 1 None

Flight Conducted Under: Part 137: Agricultural

Analysis

The pilot reported that, during the final run for the aerial application flight, he noticed the engine spooling down. He attempted to land on a nearby road but collided with the terrain, resulting in substantial damage to the fuselage. The pilot reported that there were no preaccident mechanical malfunctions or failures with the helicopter or engine that would have precluded normal operation and that the loss of engine power was due to fuel exhaustion.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's inadequate fuel planning, which resulted in fuel exhaustion and a loss of engine power.

Findings

Personnel issues Fuel planning - Pilot

Aircraft Fuel - Fluid level

Factual Information

History of Flight

Maneuvering-low-alt flying	Fuel exhaustion (Defining event)
Maneuvering-low-alt flying	Loss of engine power (total)
Emergency descent	Collision with terr/obj (non-CFIT)
Emergency descent	Off-field or emergency landing

Pilot Information

Certificate:	Commercial	Age:	70,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	Helicopter	Restraint Used:	4-point
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 2 With waivers/limitations	Last FAA Medical Exam:	March 28, 2022
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	21000 hours (Total, all aircraft), 25 hours (Total, this make and model)		

Page 2 of 5 WPR23LA118

Aircraft and Owner/Operator Information

Aircraft Make:	Bell	Registration:	N234SJ
Model/Series:	UH-1B	Aircraft Category:	Helicopter
Year of Manufacture:	1962	Amateur Built:	
Airworthiness Certificate:	Restricted (Special)	Serial Number:	388
Landing Gear Type:	Skid	Seats:	2
Date/Type of Last Inspection:	February 14, 2023 Annual	Certified Max Gross Wt.:	9500 lbs
Time Since Last Inspection:		Engines:	1 Turbo shaft
Airframe Total Time:	8295 Hrs	Engine Manufacturer:	Lycoming
ELT:	Not installed	Engine Model/Series:	T53-L-13B
Registered Owner:	PORTER FLYING SERVICES INC	Rated Power:	1200 Horsepower
Operator:	PORTER FLYING SERVICES INC	Operating Certificate(s) Held:	Agricultural aircraft (137)
Operator Does Business As:	Agricultural	Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KCIC,226 ft msl	Distance from Accident Site:	14 Nautical Miles
Observation Time:	14:47 Local	Direction from Accident Site:	76°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	9 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	150°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.09 inches Hg	Temperature/Dew Point:	13°C / -1°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Chico, CA	Type of Flight Plan Filed:	None
Destination:	Chicoc, CA	Type of Clearance:	None
Departure Time:	07:00 Local	Type of Airspace:	Class G

Page 3 of 5 WPR23LA118

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	39.727032,-122.07095(est)

Page 4 of 5 WPR23LA118

Administrative Information

Investigator In Charge (IIC): Rho, Paul

Additional Participating Persons:

Original Publish Date: June 6, 2023

Last Revision Date:

Investigation Class: Class 4

Note: The NTSB did not travel to the scene of this accident.

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=106831

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 WPR23LA118