



Aviation Investigation Final Report

Location: Bismark, North Dakota Accident Number: CEN23LA126

Date & Time: March 9, 2023, 17:45 Local Registration: N46CV

Aircraft: Beech C90 Aircraft Damage: Substantial

Defining Event: Ground collision **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Positioning

Analysis

The commercial pilot stated that a vehicle struck the right wing of the airplane as he was taxiing from the non-movement area for departure. Surveillance video showed a ground service vehicle drive across the ramp and into the right wing of the airplane. The driver of the ground vehicle stated that as she was starting to speed up on the ramp, the airplane came into view. The driver attempted to stop but slid on the ice and came to rest under the airplane's right wing. A postaccident examination of the airplane revealed substantial damage to the right wing. The pilot stated there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The ground vehicle driver's failure to see and maintain clearance from the airplane while conducting ground operations.

Findings

Personnel issues	Task monitoring/vigilance - Ground crew
Environmental issues	Snow - Ability to respond/compensate

Page 2 of 6 CEN23LA126

Factual Information

History of Flight

Taxi-to runway	Ground collision (Defining event)

Pilot Information

Certificate:	Commercial	Age:	27,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 1 Without waivers/limitations	Last FAA Medical Exam:	June 23, 2022
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	December 7, 2022
Flight Time:	1300 hours (Total, all aircraft), 92 hours (Total, this make and model), 1059 hours (Pilot In Command, all aircraft), 44 hours (Last 90 days, all aircraft), 14 hours (Last 30 days, all aircraft)		

Page 3 of 6 CEN23LA126

Aircraft and Owner/Operator Information

Aircraft Make:	Beech	Registration:	N46CV
Model/Series:	C90	Aircraft Category:	Airplane
Year of Manufacture:	1973	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	LJ-568
Landing Gear Type:	Retractable - Tricycle	Seats:	7
Date/Type of Last Inspection:	March 9, 2023 AAIP	Certified Max Gross Wt.:	9650 lbs
Time Since Last Inspection:		Engines:	2 Turbo prop
Airframe Total Time:	13607.8 Hrs at time of accident	Engine Manufacturer:	Pratt and Whitney
ELT:	C126 installed, not activated	Engine Model/Series:	PT6A-21
Registered Owner:	On file	Rated Power:	
Operator:	Executive Air Taxi Corporation	Operating Certificate(s) Held:	On-demand air taxi (135)
Operator Does Business As:	On file	Operator Designator Code:	CTYA

Meteorological Information and Flight Plan

meteorological informati			
Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KBIS,1651 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	17:15 Local	Direction from Accident Site:	3°
Lowest Cloud Condition:		Visibility	1.5 miles
Lowest Ceiling:	Broken / 2800 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	9 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	20°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.36 inches Hg	Temperature/Dew Point:	-6°C / -9°C
Precipitation and Obscuration:	Light - None - Snow		
Departure Point:	Bismark, ND	Type of Flight Plan Filed:	IFR
Destination:	Minot, ND (KMOT)	Type of Clearance:	IFR
Departure Time:		Type of Airspace:	Class D

Page 4 of 6 CEN23LA126

Airport Information

Airport: Bismark Municipal Airport BIS Runway Surface Type:

Airport Elevation:1661 ft mslRunway Surface Condition:Dry;SnowRunway Used:IFR Approach:ILS;RNAV;VOR

Runway Length/Width: VFR Approach/Landing:

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	46.776173,-100.75848(est)

Page 5 of 6 CEN23LA126

Administrative Information

Investigator In Charge (IIC): Rutt, Brian

Additional Participating Persons:

Original Publish Date: April 20, 2023

Last Revision Date:
Investigation Class: Class 4

Note: The NTSB did not travel to the scene of this accident.

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=106860

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 CEN23LA126