

Aviation Investigation Final Report

Location: Chatham, Massachusetts Accident Number: ERA23LA129

Date & Time: February 19, 2023, 10:15 Local Registration: N711PD

Aircraft: Cessna TR182 Aircraft Damage: Substantial

Defining Event: Landing gear not configured **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

At the conclusion of an uneventful flight, the pilot entered the airport traffic pattern for landing. The pilot reported that while on the downwind leg of the traffic pattern for landing, he failed to extend the landing gear and landed with the landing gear retracted. The airplane subsequently touched down on the runway and sustained substantial damage to the underside of the fuselage. The pilot reported that there were no preaccident machinal malfunctions or failure with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to lower the landing gear before touchdown.

Findings

Personnel issues Forgotten action/omission - Pilot

Personnel issues Use of equip/system - Pilot

Aircraft Gear extension and retract sys - Not used/operated

Page 2 of 6 ERA23LA129

Factual Information

History of Flight

Landing-flare/touchdown	Landing gear not configured (Defining event)

Pilot Information

Certificate:	Commercial; Flight instructor	Age:	70.Male
ocitificate.	Commercial, ringht matractor	Age.	7 O,IVICIC
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane single-engine; Instrument airplane	Toxicology Performed:	
Medical Certification:	Class 2 With waivers/limitations	Last FAA Medical Exam:	June 3, 2021
Occupational Pilot:	No	Last Flight Review or Equivalent:	September 10, 2022
Flight Time:	5285 hours (Total, all aircraft), 2571 hours (Total, this make and model), 5130 hours (Pilot In Command, all aircraft), 0 hours (Last 24 hours, all aircraft)		

Passenger Information

Certificate:		Age:	12,Female
Airplane Rating(s):		Seat Occupied:	Left
Other Aircraft Rating(s):		Restraint Used:	3-point
Instrument Rating(s):		Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	
Medical Certification:		Last FAA Medical Exam:	
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:			

Page 3 of 6 ERA23LA129

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N711PD
Model/Series:	TR182	Aircraft Category:	Airplane
Year of Manufacture:	1979	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	R18201282
Landing Gear Type:	Retractable - Tricycle	Seats:	4
Date/Type of Last Inspection:	March 11, 2022 Condition	Certified Max Gross Wt.:	3100 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	3463 Hrs as of last inspection	Engine Manufacturer:	Lycoming
ELT:	C91 installed, not activated	Engine Model/Series:	O-540-L3C5D
Registered Owner:	On file	Rated Power:	235 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	CQX,61 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	10:52 Local	Direction from Accident Site:	241°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	None / None
Wind Direction:		Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	30.39 inches Hg	Temperature/Dew Point:	8°C / -1°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	East Falmouth, MA (5B6)	Type of Flight Plan Filed:	None
Destination:	Chatham, MA (CQX)	Type of Clearance:	None
Departure Time:	09:45 Local	Type of Airspace:	Class G

Page 4 of 6 ERA23LA129

Airport Information

Airport:	CHATHAM MUNI CQX	Runway Surface Type:	Asphalt
Airport Elevation:	63 ft msl	Runway Surface Condition:	Dry
Runway Used:	24	IFR Approach:	None
Runway Length/Width:	3001 ft / 100 ft	VFR Approach/Landing:	Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	41.69055,-69.986791(est)

Page 5 of 6 ERA23LA129

Administrative Information

Investigator In Charge (IIC):	Freeze, Christopher
Additional Participating Persons:	Philippe M. Larivee; FAA/FSDO; Boston, MA
Original Publish Date:	June 15, 2023
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=106782

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ERA23LA129