



# **Aviation Investigation Final Report**

**Location:** Port Orange, Florida **Accident Number:** ERA23LA123

Date & Time: February 2, 2023, 12:00 Local Registration: N864JB

Aircraft: Piper PA46 Aircraft Damage: Substantial

**Defining Event:** Loss of control on ground **Injuries:** 2 Serious

Flight Conducted Under: Part 91: General aviation - Personal

#### **Analysis**

The pilot reported, and airport security video confirmed, that during a takeoff attempt, the right wing contacted the runway and the pilot pulled back excessively on the yoke. The airplane pitched up, stalled, and descended back on to the runway. It subsequently travelled off the end of the runway and impacted trees, before coming to rest on its side. The pilot added that in retrospect, he should have rejected the takeoff when the right wing contacted the runway. Examination of the wreckage by a Federal Aviation Administration inspector did not reveal any preimpact mechanical malfunctions, nor did the pilot report any. The inspector noted that both wings separated, and the fuselage was substantially damaged.

#### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain aircraft control during a takeoff attempt, which resulted in an aerodynamic stall, runway excursion, and collision with trees.

### **Findings**

| Personnel issues | Aircraft control - Pilot                |
|------------------|---|
| Aircraft         | Pitch control - Not attained/maintained |

Page 2 of 6 ERA23LA123

## **Factual Information**

### **History of Flight**

| Takeoff | Loss of control on ground (Defining event) |
|---------|--|
| Takeoff | Runway excursion                           |
| Takeoff | Collision with terr/obj (non-CFIT)         |

#### **Pilot Information**

| Certificate:              | Private  | Age:                                      | 46,Male             |
|---------------------------|--|---|---------------------|
| Airplane Rating(s):       | Single-engine land                                   | Seat Occupied:                            | Left                |
| Other Aircraft Rating(s): | None   | Restraint Used:                           | 3-point             |
| Instrument Rating(s):     | Airplane   | Second Pilot Present:                     | No                  |
| Instructor Rating(s):     | None   | Toxicology Performed:                     |                     |
| Medical Certification:    | Class 3 With waivers/limitations                     | Last FAA Medical Exam:                    | October 24, 2022    |
| Occupational Pilot:       | No   | Last Flight Review or Equivalent:         | September 21, 2022  |
| Flight Time:              | 459 hours (Total, all aircraft), 19 hou<br>aircraft) | urs (Last 30 days, all aircraft), 0 hours | (Last 24 hours, all |

Page 3 of 6 ERA23LA123

### **Aircraft and Owner/Operator Information**

| Aircraft Make:                | Piper  | Registration:                     | N864JB          |
|-------------------------------|--|-----------------------------------|-----------------|
| Model/Series:                 | PA46 310P  | Aircraft Category:                | Airplane        |
| Year of Manufacture:          | 1986   | Amateur Built:                    |                 |
| Airworthiness Certificate:    | Normal   | Serial Number:                    | 4608009         |
| Landing Gear Type:            | Retractable - Tricycle                                 | Seats:                            | 6               |
| Date/Type of Last Inspection: | Annual   | Certified Max Gross Wt.:          | 4100 lbs        |
| Time Since Last Inspection:   |  | Engines:                          | 1 Reciprocating |
| Airframe Total Time:          |  | Engine Manufacturer:              | Continental     |
| ELT:                          | Installed, activated, did not aid in locating accident | Engine Model/Series:              | TSIO-520        |
| Registered Owner:             | On file  | Rated Power:                      | 310 Horsepower  |
| Operator:                     | On file  | Operating Certificate(s)<br>Held: | None            |

## Meteorological Information and Flight Plan

| Conditions at Accident Site:     | Visual (VMC)                     | Condition of Light:                  | Day              |
|----------------------------------|----------------------------------|--------------------------------------|------------------|
| Observation Facility, Elevation: | KDAB,26 ft msl                   | Distance from Accident Site:         | 6 Nautical Miles |
| Observation Time:                | 11:53 Local                      | Direction from Accident Site:        | 351°             |
| <b>Lowest Cloud Condition:</b>   | Few / 5000 ft AGL                | Visibility                           | 10 miles         |
| Lowest Ceiling:                  | None                             | Visibility (RVR):                    |                  |
| Wind Speed/Gusts:                | 6 knots /                        | Turbulence Type<br>Forecast/Actual:  | None / None      |
| Wind Direction:                  | 280°                             | Turbulence Severity Forecast/Actual: | N/A / N/A        |
| Altimeter Setting:               | 30.16 inches Hg                  | Temperature/Dew Point:               | 26°C / 17°C      |
| Precipitation and Obscuration:   | No Obscuration; No Precipitation |                                      |                  |
| Departure Point:                 | Port Orange, FL                  | Type of Flight Plan Filed:           | IFR              |
| Destination:                     | Bluffton, OH (5G7)               | Type of Clearance:                   | IFR              |
| Departure Time:                  |                                  | Type of Airspace:                    | Class G          |

Page 4 of 6 ERA23LA123

### **Wreckage and Impact Information**

| Crew Injuries:         | 1 Serious | Aircraft Damage:        | Substantial               |
|------------------------|-----------|-------------------------|---------------------------|
| Passenger<br>Injuries: | 1 Serious | Aircraft Fire:          | None                      |
| Ground Injuries:       |           | Aircraft Explosion:     | None                      |
| Total Injuries:        | 2 Serious | Latitude,<br>Longitude: | 29.075329,-81.053203(est) |

Page 5 of 6 ERA23LA123

#### **Administrative Information**

| Investigator In Charge (IIC):     | Gretz, Robert  |
|-----------------------------------|--|
| Additional Participating Persons: | Robert Gonzalez Jr; FAA/FSDO; Orlando, FL              |
| Original Publish Date:            | June 15, 2023  |
| Last Revision Date:               |  |
| Investigation Class:              | Class 4  |
| Note:                             | The NTSB did not travel to the scene of this accident. |
| Investigation Docket:             | https://data.ntsb.gov/Docket?ProjectID=106675          |

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ERA23LA123