



Aviation Investigation Final Report

Location: Belen, New Mexico **Accident Number:** WPR23LA178

Date & Time: May 7, 2023, 13:40 Local Registration: N80892

Aircraft: UNIVERSAL GLOBE GC-1A Aircraft Damage: Destroyed

Defining Event: Windshear or thunderstorm **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot reported that while taking off, the wind shifted to a strong quartering tailwind. The airplane settled to the ground and the propeller contacted the runway before the landing gear could be extended by the pilot. The pilot and passenger exited the airplane unharmed. The airplane was destroyed by the postcrash fire. The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The airplane's encounter with downdraft on takeoff, which resulted in a loss of control.

Findings

Environmental issues Sudden wind shift - Awareness of condition

Personnel issues Use of equip/system - Pilot
Personnel issues Monitoring environment - Pilot

Factual Information

History of Flight

| Takeoff Windshear or thunderstorm (Defining event) |
|--|
|--|

Pilot Information

| Certificate: | Airline transport | Age: | 61,Male |
|---------------------------|--|-----------------------------------|----------------|
| Airplane Rating(s): | Single-engine land; Single-engine sea; Multi-engine land | Seat Occupied: | Left |
| Other Aircraft Rating(s): | None | Restraint Used: | Lap only |
| Instrument Rating(s): | Airplane | Second Pilot Present: | |
| Instructor Rating(s): | Airplane multi-engine; Airplane single-engine; Instrument airplane | Toxicology Performed: | |
| Medical Certification: | Class 2 With waivers/limitations | Last FAA Medical Exam: | May 3, 2022 |
| Occupational Pilot: | Yes | Last Flight Review or Equivalent: | March 15, 2023 |
| Flight Time: | 19200 hours (Total, all aircraft), 18 hours (Total, this make and model), 1700 hours (Pilot In Command, all aircraft), 79 hours (Last 90 days, all aircraft), 30 hours (Last 30 days, all aircraft), 0 hours (Last 24 hours, all aircraft) | | |

Passenger Information

| T dooringer innorma | | | |
|---------------------------|----|-----------------------------------|----------|
| Certificate: | | Age: | |
| Airplane Rating(s): | | Seat Occupied: | Right |
| Other Aircraft Rating(s): | | Restraint Used: | Lap only |
| Instrument Rating(s): | | Second Pilot Present: | |
| Instructor Rating(s): | | Toxicology Performed: | |
| Medical Certification: | | Last FAA Medical Exam: | |
| Occupational Pilot: | No | Last Flight Review or Equivalent: | |
| Flight Time: | | | |

Page 2 of 5 WPR23LA178

Aircraft and Owner/Operator Information

| Aircraft Make: | UNIVERSAL | Registration: | N80892 |
|-------------------------------|----------------------------------|-----------------------------------|--------------------|
| Model/Series: | GLOBE GC-1A | Aircraft Category: | Airplane |
| Year of Manufacture: | 1946 | Amateur Built: | |
| Airworthiness Certificate: | Normal | Serial Number: | 295 |
| Landing Gear Type: | Retractable - Tailwheel | Seats: | 2 |
| Date/Type of Last Inspection: | March 17, 2023 Annual | Certified Max Gross Wt.: | 1710 lbs |
| Time Since Last Inspection: | 18.3 Hrs | Engines: | 1 Reciprocating |
| Airframe Total Time: | 1464.1 Hrs as of last inspection | Engine Manufacturer: | Continental Motors |
| ELT: | C91 installed, not activated | Engine Model/Series: | C-125-2 |
| Registered Owner: | On file | Rated Power: | 125 Horsepower |
| Operator: | On file | Operating Certificate(s) Held: | None |

Meteorological Information and Flight Plan

| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Day |
|----------------------------------|----------------------------------|--------------------------------------|-------------------|
| Observation Facility, Elevation: | KBRG,5199 ft msl | Distance from Accident Site: | 0 Nautical Miles |
| Observation Time: | 13:35 Local | Direction from Accident Site: | 64° |
| Lowest Cloud Condition: | Clear | Visibility | 10 miles |
| Lowest Ceiling: | None | Visibility (RVR): | |
| Wind Speed/Gusts: | 6 knots / 14 knots | Turbulence Type Forecast/Actual: | None / Convective |
| Wind Direction: | 200° | Turbulence Severity Forecast/Actual: | N/A / Moderate |
| Altimeter Setting: | 30.04 inches Hg | Temperature/Dew Point: | 27°C / -10°C |
| Precipitation and Obscuration: | No Obscuration; No Precipitation | | |
| Departure Point: | Belen, NM (KBRG) | Type of Flight Plan Filed: | None |
| Destination: | Belen, NM | Type of Clearance: | None |
| Departure Time: | 13:40 Local | Type of Airspace: | Class G |

Page 3 of 5 WPR23LA178

Airport Information

| Airport: | BELEN RGNL BRG | Runway Surface Type: | Asphalt |
|----------------------|-----------------|----------------------------------|-----------|
| Airport Elevation: | 5199 ft msl | Runway Surface Condition: | Dry |
| Runway Used: | 31 | IFR Approach: | None |
| Runway Length/Width: | 5280 ft / 75 ft | VFR Approach/Landing: | Full stop |

Wreckage and Impact Information

| Crew Injuries: | 1 None | Aircraft Damage: | Destroyed |
|------------------------|--------|-------------------------|----------------------|
| Passenger Injuries: | 1 None | Aircraft Fire: | On-ground |
| Ground Injuries: | | Aircraft Explosion: | None |
| Total Injuries: | 2 None | Latitude, Longitude: | 34.645862,-106.83634 |

Page 4 of 5 WPR23LA178

Administrative Information

| Investigator In Charge (IIC): | Johnson, Scott |
|-----------------------------------|---|
| Additional Participating Persons: | Gary Medina; Federal Aviation Administration; Albuquerque, NM |
| Original Publish Date: | September 8, 2023 |
| Last Revision Date: | |
| Investigation Class: | Class 4 |
| Note: | The NTSB did not travel to the scene of this accident. |
| Investigation Docket: | https://data.ntsb.gov/Docket?ProjectID=114703 |

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 WPR23LA178