

Aviation Investigation Final Report

Location: Fernandina Beach, Florida **Accident Number:** ERA23LA150

Date & Time: February 17, 2023, 18:19 Local Registration: N740NG

Aircraft: CIRRUS DESIGN CORP SR22 Aircraft Damage: Substantial

Defining Event: Loss of control in flight **Injuries:** 3 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot reported that after conducting an instrument approach, the airplane descended out of the clouds at an altitude of about 800 feet above the ground and the pilot had a clear view of the runway. The pilot described that the descent was "uneventful though blustery." During the subsequent landing, while the airplane was slow and in a nose up pitch attitude, he encountered a sudden wind gust and the airplane subsequently struck a runway identifier sign. The airplane's left wing and fuselage were substantially damaged during the collision. The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain control of the airplane while landing in gusting crosswind conditions, with resulted in a runway excursion and collision with a runway identifier sign.

Findings

Personnel issues Aircraft control - Pilot

Environmental issues Gusts - Response/compensation

Page 2 of 6 ERA23LA150

Factual Information

History of Flight

Landing-flare/touchdown	Loss of control in flight (Defining event)

Landing Runway excursion

Pilot Information

Certificate:	Private	Age:	65,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	BasicMed Without waivers/limitations	Last FAA Medical Exam:	February 8, 2022
Occupational Pilot:	No	Last Flight Review or Equivalent:	November 4, 2022
Flight Time:	446 hours (Total, all aircraft), 162 hours (Total, this make and model), 151 hours (Pilot In Command, all aircraft)		

Passenger Information

Certificate:	Age:	Female
Airplane Rating(s):	Seat Occupied:	Right
Other Aircraft Rating(s):	Restraint Used:	Unknown
Instrument Rating(s):	Second Pilot Present:	No
Instructor Rating(s):	Toxicology Performed:	
Medical Certification:	Last FAA Medical Exam:	
Occupational Pilot:	Last Flight Review or Equivalent:	
Flight Time:		

Page 3 of 6 ERA23LA150

Passenger Information

Certificate:	Age:	Male
Airplane Rating(s):	Seat Occupied:	Left
Other Aircraft Rating(s):	Restraint Used:	Unknown
Instrument Rating(s):	Second Pilot Present:	No
Instructor Rating(s):	Toxicology Performed:	
Medical Certification:	Last FAA Medical Exam:	
Occupational Pilot:	Last Flight Review or Equivalent:	
Flight Time:		

Aircraft and Owner/Operator Information

Aircraft Make:	CIRRUS DESIGN CORP	Registration:	N740NG
Model/Series:	SR22	Aircraft Category:	Airplane
Year of Manufacture:	2006	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	2032
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	November 28, 2022 Annual	Certified Max Gross Wt.:	3400 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	1895 Hrs at time of accident	Engine Manufacturer:	Continental
ELT:	C126 installed, not activated	Engine Model/Series:	IO-550N
Registered Owner:	ADROIT REAL ESTATE HOLDINGS LLC	Rated Power:	310 Horsepower
Operator:	ADROIT REAL ESTATE HOLDINGS LLC	Operating Certificate(s) Held:	None

Page 4 of 6 ERA23LA150

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KFHB,17 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	16:15 Local	Direction from Accident Site:	319°
Lowest Cloud Condition:	Scattered / 2700 ft AGL	Visibility	10 miles
Lowest Ceiling:	Broken / 3400 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	18 knots / 25 knots	Turbulence Type Forecast/Actual:	Unknown / Unknown
Wind Direction:	290°	Turbulence Severity Forecast/Actual:	Unknown / Moderate
Altimeter Setting:	29.99 inches Hg	Temperature/Dew Point:	22°C / 19°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Peachtree Clty, GA (FFC)	Type of Flight Plan Filed:	None
Destination:	Fernandina Beach, FL	Type of Clearance:	IFR
Departure Time:	16:51 Local	Type of Airspace:	Class G

Airport Information

Airport:	Fernendina Beach FHB	Runway Surface Type:	Asphalt
Airport Elevation:	16 ft msl	Runway Surface Condition:	Wet
Runway Used:	22	IFR Approach:	RNAV
Runway Length/Width:	5301 ft / 100 ft	VFR Approach/Landing:	

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	2 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	3 None	Latitude, Longitude:	30.612298,-81.462179(est)

Page 5 of 6 ERA23LA150

Administrative Information

Investigator In Charge (IIC):	Freeze, Christopher
Additional Participating Persons:	Jennifer Viteritto; FAA/FSDO; Orlando, FL
Original Publish Date:	June 23, 2023
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=106875

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ERA23LA150