



# **Aviation Investigation Final Report**

Location: Santa Ana, California Accident Number: WPR23LA146

Date & Time: April 1, 2023, 13:43 Local Registration: N1399U

Aircraft: Cessna 172M Aircraft Damage: Substantial

**Defining Event:** Aircraft wake turb encounter **Injuries:** N/A

Flight Conducted Under: Part 91: General aviation - Instructional

### **Analysis**

The flight instructor reported that while practicing crosswind landings with his student, the tower advised the pilot of wake turbulence from a commercial airliner on the parallel runway. They flew a steeper approach but noticed a moderate right quartering headwind on the windsock. At about 100 feet above ground level the airplane encountered wake turbulence and banked sharply to the right. Both pilots added full left aileron and applied backpressure to the yoke as the airplane contacted the terrain. The airplane sustained substantial damage to the right wing.

The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The flight instructor's failure to maintain clearance from a medium category commercial airliner which resulted in an encounter with wake turbulence and subsequent loss of control resulting in impact with terrain.

### **Findings**

**Environmental issues** Wake turbulence - Ability to respond/compensate

Aircraft Descent/approach/glide path - Not attained/maintained

Personnel issues Aircraft control - Student/instructed pilot

Page 2 of 6 WPR23LA146

## **Factual Information**

### **History of Flight**

Canding Allician wake turb encounter (Denning event)	Landing	Aircraft wake turb encounter (Defining event)
--	---------	---

#### **Pilot Information**

Certificate:	Commercial	Age:	21,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane single-engine; Instrument airplane	Toxicology Performed:	
Medical Certification:	Class 1 Without waivers/limitations	Last FAA Medical Exam:	June 13, 2019
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	December 8, 2021
Flight Time:	891.5 hours (Total, all aircraft), 890.5 hours (Total, this make and model), 862.3 hours (Pilot In Command, all aircraft), 175.2 hours (Last 90 days, all aircraft), 64.5 hours (Last 30 days, all aircraft), 7.5 hours (Last 24 hours, all aircraft)		

#### **Pilot Information**

Certificate:	Student	Age:	26,Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	None	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 1 Without waivers/limitations	Last FAA Medical Exam:	January 30, 2023
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	0 hours (Total, all aircraft), 0 hours (Total, this make and model)		

Page 3 of 6 WPR23LA146

### **Aircraft and Owner/Operator Information**

### Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KSNA,43 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	13:53 Local	Direction from Accident Site:	13°
<b>Lowest Cloud Condition:</b>	Few / 3500 ft AGL	Visibility	10 miles
Lowest Ceiling:		Visibility (RVR):	
Wind Speed/Gusts:	9 knots /	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	220°	Turbulence Severity Forecast/Actual:	N/A / Severe
Altimeter Setting:	30.12 inches Hg	Temperature/Dew Point:	19°C / 7°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Santa Ana, CA (KSNA)	Type of Flight Plan Filed:	None
Destination:	Santa Ana, CA	Type of Clearance:	VFR
Departure Time:	13:43 Local	Type of Airspace:	Class C

Page 4 of 6 WPR23LA146

### **Airport Information**

Airport:	John Wayne/Orange County Airport KSNA	Runway Surface Type:	Asphalt
Airport Elevation:	56 ft msl	Runway Surface Condition:	Dry
Runway Used:	20L	IFR Approach:	Unknown
Runway Length/Width:	2886 ft / 75 ft	VFR Approach/Landing:	Touch and go;Traffic pattern

### Wreckage and Impact Information

Crew Injuries:	N/A	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	N/A	Latitude, Longitude:	33.675662,-117.86823

Page 5 of 6 WPR23LA146

#### **Administrative Information**

Investigator In Charge (IIC):	Johnson, Scott
Additional Participating Persons:	Marcus Giordano; Federal Aviation Administration; Sacramento, CA
Original Publish Date:	July 7, 2023
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=106999

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 WPR23LA146