



Aviation Investigation Final Report

Location: Bucyrus, Ohio Accident Number: ERA23LA377

Date & Time: September 21, 2023, 18:50 Local Registration: N2067Q

Aircraft: AVIAN BALLOON SKYHAWK Aircraft Damage: Minor

Defining Event: Loss of control on ground **Injuries:** 1 Serious, 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The balloon pilot reported that after a local sightseeing flight, she maneuvered and descended toward the landing zone that was an open field that had power lines nearby. After clearing the power lines, the pilot further descended and just prior to impact she "added a small amount of heat," however, the basket bounced twice and tipped over onto its side. The pilot then completely deflated the balloon to prevent the basket from getting dragged on the ground. During the bounced landing and basket tip over, one of the passengers fell to the bottom of the basket, which resulted in a serious injury to her right leg. The pilot reported that there were no preimpact mechanical malfunctions or failures with the balloon that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The balloon pilot's bounced landing, which resulted in the basket tipping over and a serious injury to a passenger.

Findings

Personnel issues	Aircraft control - Pilot

Aircraft Landing flare - Not attained/maintained

Page 2 of 6 ERA23LA377

Factual Information

History of Flight

Landing-flare/touchdown Loss of control on ground (Defining event)
--

Pilot Information

Certificate:	Private	Age:	67,Female
Airplane Rating(s):	None	Seat Occupied:	None
Other Aircraft Rating(s):	Balloon	Restraint Used:	None
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	None None	Last FAA Medical Exam:	
Occupational Pilot:	No	Last Flight Review or Equivalent:	June 24, 2022
Flight Time:	375 hours (Total, all aircraft), 375 hours (Total, this make and model), 360 hours (Pilot In Command, all aircraft), 9 hours (Last 90 days, all aircraft), 5 hours (Last 30 days, all aircraft)		

Passenger Information

Certificate:		Age:	Female
Airplane Rating(s):		Seat Occupied:	Left
Other Aircraft Rating(s):		Restraint Used:	None
Instrument Rating(s):		Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	
Medical Certification:		Last FAA Medical Exam:	
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:			

Page 3 of 6 ERA23LA377

Passenger Information

Certificate:		Age:	Female
Airplane Rating(s):		Seat Occupied:	Right
Other Aircraft Rating(s):		Restraint Used:	None
Instrument Rating(s):		Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	
Medical Certification:		Last FAA Medical Exam:	
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:			

Aircraft and Owner/Operator Information

Aircraft Make:	AVIAN BALLOON	Registration:	N2067Q
Model/Series:	SKYHAWK NO SERIES	Aircraft Category:	Balloon
Year of Manufacture:	1999	Amateur Built:	
Airworthiness Certificate:	Balloon	Serial Number:	207
Landing Gear Type:		Seats:	4
Date/Type of Last Inspection:	May 5, 2023 Annual	Certified Max Gross Wt.:	1350 lbs
Time Since Last Inspection:		Engines:	1 Unknown
Airframe Total Time:	350 Hrs	Engine Manufacturer:	AVIAN
ELT:	Not installed	Engine Model/Series:	TURBO 8
Registered Owner:	On file	Rated Power:	
Operator:	On file	Operating Certificate(s) Held:	None

Page 4 of 6 ERA23LA377

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	MFD,1289 ft msl	Distance from Accident Site:	18 Nautical Miles
Observation Time:	18:52 Local	Direction from Accident Site:	100°
Lowest Cloud Condition:	Scattered / 5500 ft AGL	Visibility	10 miles
Lowest Ceiling:		Visibility (RVR):	
Wind Speed/Gusts:	3 knots /	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	90°	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	30.25 inches Hg	Temperature/Dew Point:	23°C / 13°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Bucyrus, OH	Type of Flight Plan Filed:	None
Destination:	Bucyrus, OH	Type of Clearance:	None
Departure Time:		Type of Airspace:	Class G

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Minor
Passenger Injuries:	1 Serious, 1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Serious, 2 None	Latitude, Longitude:	40.870927,-82.902091(est)

Page 5 of 6 ERA23LA377

Administrative Information

Investigator In Charge (IIC):	Gerhardt, Adam
Additional Participating Persons:	Tomash V. Bokotey; FAA/ FSDO; Cleveland, OH
Original Publish Date:	December 21, 2023
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=193120

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ERA23LA377