





Injuries:



1 Minor

PIPELINE

Aviation Investigation Final Report

Location: Casper, Wyoming Accident Number: WPR23LA277

Date & Time: July 17, 2023, 07:20 Local Registration: N277GH

Aircraft: EVOLUTION AIRCRAFT INC REVOLT Aircraft Damage: Substantial

Aircraft wake turb encounter

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

Defining Event:

The pilot reported being cleared to land by air traffic control and reported being cautioned of wake turbulence by an airplane that landed ahead in sequence. The pilot aimed to touchdown at a point beyond the presence of the wake turbulence. The airplane encountered light turbulence prior to landing and contacted the runway misaligned with the runway centerline. The pilot applied opposite input correction which produced a roll force resulting in the right wing contacting the ground, substantially damaging the airplane. The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's loss of directional control during landing after encountering wake turbulence.

Findings

Personnel issues	Aircraft control - Pilot
reisoillei issues	All Clait Colltion - Filot

Aircraft Landing flare - Capability exceeded

Page 2 of 5 WPR23LA277

Factual Information

History of Flight

Landing-flare/touchdown Aircraft wake turb encounter (Defining event)

Pilot Information

Certificate:	Private	Age:	61
Airplane Rating(s):	Single-engine land; Single-engine sea	Seat Occupied:	Front
Other Aircraft Rating(s):	Glider	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	
Instructor Rating(s):	Sport pilot	Toxicology Performed:	
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	September 26, 2022
Occupational Pilot:	No	Last Flight Review or Equivalent:	November 8, 2021
Flight Time:	2000 hours (Total, all aircraft), 25 hours (Total, this make and model), 40 hours (Last 90 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	EVOLUTION AIRCRAFT INC	Registration:	N277GH
		_	
Model/Series:	REVOLT	Aircraft Category:	Weight-shift
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	001022
Landing Gear Type:	Tricycle	Seats:	2
Date/Type of Last Inspection:	Annual	Certified Max Gross Wt.:	
Time Since Last Inspection:	15 Hrs	Engines:	1
Airframe Total Time:	74.7 Hrs at time of accident	Engine Manufacturer:	
ELT:		Engine Model/Series:	
Registered Owner:	KC CONSTRUCTION	Rated Power:	
Operator:	KC CONSTRUCTION	Operating Certificate(s) Held:	None

Page 3 of 5 WPR23LA277

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KCPR,5290 ft msl	Distance from Accident Site:	1 Nautical Miles
Observation Time:	07:53 Local	Direction from Accident Site:	224°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.14 inches Hg	Temperature/Dew Point:	19°C / 9°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Casper, WY	Type of Flight Plan Filed:	None
Destination:	Casper, WY (CPR)	Type of Clearance:	VFR
Departure Time:	08:00 Local	Type of Airspace:	Class D

Airport Information

Airport:	Casper/Natrona County Airport KCPR	Runway Surface Type:	Asphalt
Airport Elevation:	5344 ft msl	Runway Surface Condition:	Dry
Runway Used:	03	IFR Approach:	None
Runway Length/Width:	10165 ft / 150 ft	VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	42.905861,-106.46363

Page 4 of 5 WPR23LA277

Administrative Information

Investigator In Charge (IIC):

Basti, Paymaun

Bruce Hanson; FAA FSFO; Casper, WY

Persons:

Original Publish Date:

January 4, 2024

Last Revision Date:

Investigation Class:

Class 4

Note:

The NTSB did not travel to the scene of this accident.

Investigation Docket:

https://data.ntsb.gov/Docket?ProjectID=192666

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 WPR23LA277