



Aviation Investigation Final Report

Location: Marble Canyon, Arizona Accident Number: WPR23LA335

Date & Time: September 4, 2023, 10:30 Local Registration: N9328U

Aircraft: Cessna 150M Aircraft Damage: Substantial

Defining Event: Collision with terr/obj (non-CFIT) **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot reported that while departing, the airplane climbed to an altitude of 20 feet above the ground. The airspeed began decreasing, and the airplane started descending. The pilot pitched down as the stall warning sounded. The airplane impacted the terrain, collapsing the nose wheel and substantially damaging the left wing. The pilot stated the airplane had encountered windshear and that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's loss of airplane control after an encounter with windshear during takeoff which resulted in collision with terrain.

Findings

Environmental issues Windshear - Contributed to outcome

Aircraft Climb rate - Attain/maintain not possible

Factual Information

History of Flight

Takeoff	Other weather encounter
Takeoff	Collision with terr/obj (non-CFIT) (Defining event)

Pilot Information

Certificate:	Commercial; Flight instructor; Private	Age:	22,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	None	Restraint Used:	None
Instrument Rating(s):	Airplane	Second Pilot Present:	
Instructor Rating(s):	Airplane single-engine; Instrument airplane	Toxicology Performed:	Yes
Medical Certification:	Class 1 With waivers/limitations	Last FAA Medical Exam:	November 3, 2023
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	November 30, 2022
Flight Time:	1032 hours (Total, all aircraft), 194 hours (Total, this make and model), 882 hours (Pilot In Command, all aircraft), 237 hours (Last 90 days, all aircraft), 108 hours (Last 30 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

Co-pilot Information

Certificate:	Private	Age:	17,Male
Airplane Rating(s):	Single-engine sea	Seat Occupied:	Left
Other Aircraft Rating(s):		Restraint Used:	None
Instrument Rating(s):	None	Second Pilot Present:	
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 1 With waivers/limitations	Last FAA Medical Exam:	November 15, 2022
Occupational Pilot:	No	Last Flight Review or Equivalent:	April 7, 2023
Flight Time:	80 hours (Total, all aircraft), 7 hours (Total, this make and model), 46 hours (Pilot In Command, all aircraft), 29 hours (Last 90 days, all aircraft), 12 hours (Last 30 days, all aircraft)		

Page 2 of 5 WPR23LA335

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N9328U
Model/Series:	150M	Aircraft Category:	Airplane
Year of Manufacture:	1976	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	15078277
Landing Gear Type:	Tricycle	Seats:	2
Date/Type of Last Inspection:	August 20, 2023 Annual	Certified Max Gross Wt.:	1600 lbs
Time Since Last Inspection:	49 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	4614.5 Hrs as of last inspection	Engine Manufacturer:	Continental
ELT:	Installed, not activated	Engine Model/Series:	O-200-A
Registered Owner:	On file	Rated Power:	100 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Visual (VMC)	Condition of Light:	Day
KPGA,4288 ft msl	Distance from Accident Site:	11 Nautical Miles
10:53 Local	Direction from Accident Site:	55°
Few / 7500 ft AGL	Visibility	10 miles
	Visibility (RVR):	
/	Turbulence Type Forecast/Actual:	None / None
	Turbulence Severity Forecast/Actual:	N/A / N/A
29.97 inches Hg	Temperature/Dew Point:	26°C / 11°C
No Obscuration; No Precipitation		
San Juan, UT (Noki)	Type of Flight Plan Filed:	None
Marble Canyon, AZ (L41)	Type of Clearance:	VFR;None
10:00 Local	Type of Airspace:	Class G
	Visual (VMC) KPGA,4288 ft msl 10:53 Local Few / 7500 ft AGL / 29.97 inches Hg No Obscuration; No Precipital San Juan, UT (Noki) Marble Canyon, AZ (L41)	Visual (VMC) KPGA,4288 ft msl Distance from Accident Site: 10:53 Local Direction from Accident Site: Few / 7500 ft AGL Visibility Visibility (RVR): / Turbulence Type Forecast/Actual: Turbulence Severity Forecast/Actual: 29.97 inches Hg Temperature/Dew Point: No Obscuration; No Precipitation San Juan, UT (Noki) Type of Flight Plan Filed: Marble Canyon, AZ (L41) Type of Clearance:

Page 3 of 5 WPR23LA335

Airport Information

Airport:	MARBLE CANYON L41	Runway Surface Type:	Asphalt
Airport Elevation:	3603 ft msl	Runway Surface Condition:	Dry
Runway Used:	21	IFR Approach:	None
Runway Length/Width:	3715 ft / 35 ft	VFR Approach/Landing:	Full stop;Stop and go;Straight-in

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	36.810806,-111.64444

Page 4 of 5 WPR23LA335

Administrative Information

Investigator In Charge (IIC):	Johnson, Scott
Additional Participating Persons:	Michael McComb; Federal Aviation Administration; Las Vegas, NV
Original Publish Date:	January 10, 2024
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=193012

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 WPR23LA335