



# **Aviation Investigation Final Report**

Location: Riesel, Texas Accident Number: CEN24LA025

Date & Time: October 6, 2023, 16:30 Local Registration: N2444H

Aircraft: Cessna 172R Aircraft Damage: Substantial

**Defining Event:** Birdstrike **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Instructional

### **Analysis**

The flight instructor and student pilot were conducting a local instructional flight and saw several large birds in front of the airplane. They attempted to avoid the birds but were unable, and one bird collided with the left wing. The flight instructor assumed control of the airplane, which was difficult to control, and returned to the airport for an uneventful landing. The airplane sustained substantial damage to the left wing.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

An in-flight collision with a bird.

#### **Findings**

**Environmental issues** 

Animal(s)/bird(s) - Effect on equipment

## **Factual Information**

### **History of Flight**

Maneuvering	Birdstrike (Defining event)	
-------------	-----------------------------	--

#### **Pilot Information**

Certificate:	Commercial; Flight instructor; Remote	Age:	23,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane single-engine	Toxicology Performed:	Yes
Medical Certification:	Class 1 Without waivers/limitations	Last FAA Medical Exam:	August 22, 2023
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	March 7, 2023
Flight Time:	465 hours (Total, all aircraft), 400 hours (Total, this make and model), 370 hours (Pilot In Command, all aircraft), 94 hours (Last 90 days, all aircraft)		

#### **Student pilot Information**

•			
Certificate:	Student	Age:	18,Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	None	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 1 Without waivers/limitations	Last FAA Medical Exam:	
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	22.4 hours (Total, all aircraft), 16.9 hours (Total, this make and model), 16.9 hours (Last 90 days, all aircraft), 5.8 hours (Last 30 days, all aircraft)		

Page 2 of 5 CEN24LA025

### **Aircraft and Owner/Operator Information**

Cessna	Registration:	N2444H
172R	Aircraft Category:	Airplane
2000	Amateur Built:	
Normal	Serial Number:	17280874
Tricycle	Seats:	4
September 28, 2023 100 hour	Certified Max Gross Wt.:	2558 lbs
	Engines:	1 Reciprocating
1641 Hrs at time of accident	Engine Manufacturer:	Lycoming
C126 installed, not activated	Engine Model/Series:	10-360
CHRISTIANSEN AVIATION LLC	Rated Power:	180 Horsepower
Texas State Technical College	Operating Certificate(s) Held:	Pilot school (141)
	172R 2000  Normal  Tricycle  September 28, 2023 100 hour  1641 Hrs at time of accident C126 installed, not activated CHRISTIANSEN AVIATION LLC	172R Aircraft Category:  2000 Amateur Built:  Normal Serial Number:  Tricycle Seats:  September 28, 2023 100 hour Certified Max Gross Wt.:  Engines:  1641 Hrs at time of accident Engine Manufacturer:  C126 installed, not activated Engine Model/Series:  CHRISTIANSEN AVIATION LLC Rated Power:  Texas State Technical College Operating Certificate(s)

### Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
<b>Lowest Cloud Condition:</b>	Few / 4500 ft AGL	Visibility	10 miles
Lowest Ceiling:		Visibility (RVR):	
Wind Speed/Gusts:	8 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	360°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.14 inches Hg	Temperature/Dew Point:	29°C / 13°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Riesel, TX	Type of Flight Plan Filed:	None
Destination:	Riesel, TX	Type of Clearance:	VFR
Departure Time:		Type of Airspace:	Class E

Page 3 of 5 CEN24LA025

### Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	31.429098,-96.982644

Page 4 of 5 CEN24LA025

#### **Administrative Information**

Investigator In Charge (IIC):	Lindberg, Joshua
Additional Participating Persons:	Elvin Osorio; Federal Aviation Administration ; Irving, TX
Original Publish Date:	November 16, 2023
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=193309

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 CEN24LA025