



Aviation Investigation Final Report

Location: Kinston, North Carolina Accident Number: ERA23LA152

Date & Time: March 5, 2023, 00:30 UTC Registration: N2527L

Aircraft: Cessna 172 Aircraft Damage: Substantial

Defining Event: Wildlife encounter (non-bird) **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Instructional

Analysis

The flight instructor reported that while performing a touch-and-go landing at night, just prior to rotation speed, the pilot receiving instruction noticed a deer coming from the infield area. The flight instructor also saw a deer and heard a "clump" noise. The flight instructor reduced the engine power to idle and exited the runway. After taxiing to the ramp, the pilot and flight instructor noted damage to the airplane and subsequently airport operations personnel found one deceased and one injured deer near the landing runway. The deer strike resulted in substantial damage to the left horizontal stabilizer. The flight instructor reported that there were no preaccident mechanical malfunctions or failures with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The airplane's impact with two deer while performing a takeoff at night.

Findings

Environmental issues Animal(s)/bird(s) - Effect on equipment

Factual Information

History of Flight

Takeoff Wildlife encounter (non-bird) (Defining event)
--

Flight instructor Information

Certificate:	Commercial; Flight instructor; Remote	Age:	24,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	None	Restraint Used:	Lap only
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane single-engine	Toxicology Performed:	
Medical Certification:	Class 2 With waivers/limitations	Last FAA Medical Exam:	November 30, 2022
Occupational Pilot:	No	Last Flight Review or Equivalent:	January 12, 2022
Flight Time:	1790 hours (Total, all aircraft), 150 hours (Total, this make and model), 180 hours (Pilot In Command, all aircraft), 70 hours (Last 90 days, all aircraft), 30 hours (Last 30 days, all aircraft)		

Student pilot Information

Certificate:	Private	Age:	33,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Lap only
Instrument Rating(s):	None	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	December 23, 2019
Occupational Pilot:	No	Last Flight Review or Equivalent:	June 30, 2022
Flight Time:	339 hours (Total, all aircraft), 3 hours (Total, this make and model), 291 hours (Pilot In Command, all aircraft), 14 hours (Last 90 days, all aircraft)		

Page 2 of 5 ERA23LA152

Aircraft and Owner/Operator Information

Cessna	Registration:	N2527L
172 H	Aircraft Category:	Airplane
1966	Amateur Built:	
Normal	Serial Number:	17255727
Tricycle	Seats:	4
January 1, 2023 100 hour	Certified Max Gross Wt.:	2200 lbs
	Engines:	1 Reciprocating
2325 Hrs as of last inspection	Engine Manufacturer:	Lycoming
Installed, not activated	Engine Model/Series:	0-360-A1A
MAST AVIATION LLC	Rated Power:	180 Horsepower
MAST AVIATION LLC	Operating Certificate(s) Held:	None
	172 H 1966 Normal Tricycle January 1, 2023 100 hour 2325 Hrs as of last inspection Installed, not activated MAST AVIATION LLC	172 H Aircraft Category: 1966 Amateur Built: Normal Serial Number: Tricycle Seats: January 1, 2023 100 hour Certified Max Gross Wt.: Engines: 2325 Hrs as of last inspection Installed, not activated Engine Manufacturer: Installed, Not activated MAST AVIATION LLC Rated Power: MAST AVIATION LLC Operating Certificate(s)

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Night/bright
Observation Facility, Elevation:	ISO,94 ft msl	Distance from Accident Site:	1 Nautical Miles
Observation Time:	19:56 Local	Direction from Accident Site:	234°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	7 knots /	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	180°	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	30.22 inches Hg	Temperature/Dew Point:	12°C / 5°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	South Boston, VA (W78)	Type of Flight Plan Filed:	None
Destination:	Kinston, NC	Type of Clearance:	VFR
Departure Time:		Type of Airspace:	Class D

Page 3 of 5 ERA23LA152

Airport Information

Airport:	KINSTON REGIONAL JETPORT AT STALLINGS FIELD ISO	Runway Surface Type:	Asphalt
Airport Elevation:	92 ft msl	Runway Surface Condition:	Dry
Runway Used:	23	IFR Approach:	None
Runway Length/Width:	11498 ft / 150 ft	VFR Approach/Landing:	Touch and go

Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	35.330336,-77.60979(est)

Page 4 of 5 ERA23LA152

Administrative Information

Investigator In Charge (IIC):	Young, Joshua
Additional Participating Persons:	Corey Paczkowski; FAA/FSDO; Greensboro, NC
Original Publish Date:	June 23, 2023
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=106900

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 ERA23LA152