



Aviation Investigation Final Report

Location: Needles, California Accident Number: WPR23LA363

Date & Time: August 13, 2023, 15:00 Local Registration: N2957N

Aircraft: Piper PA-32-300 Aircraft Damage: Substantial

Defining Event: Runway excursion **Injuries:** 4 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot stated that during initial takeoff climb, the airplane encountered windshear. He was unable to regain control and the airplane touched down hard on the paved runway. The airplane then veered off to the left of the runway and came to rest with the right main and nose landing gear separated from the fuselage. As a result of the impact, the spar sustained substantial damage. The pilot reported no pre impact mechanical malfunctions or failures that would have precluded normal operation.

The pilot did not submit the National Transportation Safety Board Pilot/Operator Aircraft Accident/Incident Report Form 6120.1.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

An encounter with windshear during the initial climb after takeoff, resulting in a loss of control and a subsequent hard landing.

Findings

Environmental issues Windsh	ear - Ability to respond/compensate
-----------------------------	-------------------------------------

Personnel issues Aircraft control - Pilot

Page 2 of 5 WPR23LA363

Factual Information

History of Flight

Takeoff Runway excursion (Defining event)	
---	--

Pilot Information

Certificate:	Private	Age:	73,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Unknown
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	August 1, 2022
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:			

Aircraft and Owner/Operator Information

Aircraft Make:	Piper	Registration:	N2957N
Model/Series:	PA-32-300	Aircraft Category:	Airplane
Year of Manufacture:	1979	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	32-7940228
Landing Gear Type:	Tricycle	Seats:	6
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	3400 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	Lycoming
ELT:		Engine Model/Series:	IO-540-K1A5
Registered Owner:	On file	Rated Power:	300
Operator:	On file	Operating Certificate(s) Held:	None

Page 3 of 5 WPR23LA363

Meteorological Information and Flight Plan

Conditions at Accident Site:Visual (VMC)Condition of Light:DayObservation Facility, Elevation:KHII,782 ft mslDistance from Accident Site:5 Nautical MilesObservation Time:14:55 LocalDirection from Accident Site:55°Lowest Cloud Condition:ClearVisibilityLowest Ceiling:NoneVisibility (RVR):Wind Speed/Gusts:8 knots /Turbulence Type Forecast/Actual:None / None / NoneWind Direction:140°Turbulence Severity Forecast/Actual:N/A / N/AAltimeter Setting:29.81 inches HgTemperature/Dew Point:42°C / 7°CPrecipitation and Obscuration:Departure Point:Needles, CAType of Flight Plan Filed:NoneDestination:Type of Clearance:None				
Observation Time: 14:55 Local Direction from Accident Site: 55° Lowest Cloud Condition: Clear Visibility Lowest Ceiling: None Visibility (RVR): Wind Speed/Gusts: 8 knots / Turbulence Type Forecast/Actual: Wind Direction: 140° Turbulence Severity Forecast/Actual: Altimeter Setting: 29.81 inches Hg Temperature/Dew Point: 42°C / 7°C Precipitation and Obscuration: Departure Point: Needles, CA Type of Flight Plan Filed: None	Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Lowest Cloud Condition: Clear Visibility Lowest Ceiling: None Visibility (RVR): Wind Speed/Gusts: 8 knots / Turbulence Type Forecast/Actual: None / None Wind Direction: 140° Turbulence Severity Forecast/Actual: N/A / N/A Altimeter Setting: 29.81 inches Hg Temperature/Dew Point: 42°C / 7°C Precipitation and Obscuration: Departure Point: Needles, CA Type of Flight Plan Filed: None	Observation Facility, Elevation:	KHII,782 ft msl	Distance from Accident Site:	5 Nautical Miles
Lowest Ceiling: Wind Speed/Gusts: 8 knots / Turbulence Type Forecast/Actual: None / None None / None Wind Direction: 140° Turbulence Severity Forecast/Actual: N/A / N/A Altimeter Setting: 29.81 inches Hg Temperature/Dew Point: 42°C / 7°C Precipitation and Obscuration: Departure Point: Needles, CA Type of Flight Plan Filed: None	Observation Time:	14:55 Local	Direction from Accident Site:	55°
Wind Speed/Gusts: 8 knots / Turbulence Type Forecast/Actual: None / None Wind Direction: 140° Turbulence Severity Forecast/Actual: N/A / N/A Altimeter Setting: 29.81 inches Hg Temperature/Dew Point: 42°C / 7°C Precipitation and Obscuration: Departure Point: Needles, CA Type of Flight Plan Filed: None	Lowest Cloud Condition:	Clear	Visibility	
Wind Direction: 140° Turbulence Severity Forecast/Actual: Altimeter Setting: 29.81 inches Hg Temperature/Dew Point: 42°C / 7°C Precipitation and Obscuration: Departure Point: Needles, CA Type of Flight Plan Filed: None	Lowest Ceiling:	None	Visibility (RVR):	
Forecast/Actual: Altimeter Setting: 29.81 inches Hg Temperature/Dew Point: 42°C / 7°C Precipitation and Obscuration: Departure Point: Needles, CA Type of Flight Plan Filed: None	Wind Speed/Gusts:	8 knots /	- -	None / None
Precipitation and Obscuration: Departure Point: Needles, CA Type of Flight Plan Filed: None	Wind Direction:	140°	•	N/A / N/A
Departure Point: Needles, CA Type of Flight Plan Filed: None	Altimeter Setting:	29.81 inches Hg	Temperature/Dew Point:	42°C / 7°C
	Precipitation and Obscuration:			
Destination: Type of Clearance: None	Departure Point:	Needles, CA	Type of Flight Plan Filed:	None
	Destination:		Type of Clearance:	None
Departure Time: Type of Airspace:	Departure Time:		Type of Airspace:	

Airport Information

Airport:	CHEMEHUEVI VALLEY 49X	Runway Surface Type:	Asphalt
Airport Elevation:	638 ft msl	Runway Surface Condition:	Dry
Runway Used:	16/34	IFR Approach:	None
Runway Length/Width:	5000 ft / 75 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	3 None	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	4 None	Latitude, Longitude:	34.527857,-114.43186

Page 4 of 5 WPR23LA363

Administrative Information

Investigator In Charge (IIC):	Keliher, Zoe
Additional Participating Persons:	Robert Michaelson; Federal Aviation Administration; Riverside, CA
Original Publish Date:	April 4, 2024
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=193497

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 WPR23LA363