



# **Aviation Investigation Final Report**

Location: Grand Prairie, Texas Accident Number: CEN23LA116

Date & Time: February 19, 2023, 18:10 Local Registration: N4210D

Aircraft: Beech G35 Aircraft Damage: Substantial

**Defining Event:** Landing gear not configured **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Personal

#### **Analysis**

The pilot reported that he forgot to put down the landing gear and that he landed with the gear retracted. The airplane slid off the runway before it came to a rest. The airplane sustained substantial damage to the lower fuselage. The pilot reported there were no mechanical malfunctions or failures that would have precluded normal operations.

#### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to extend the landing gear before landing.

#### **Findings**

Personnel issues Forgotten action/omission - Pilot

Personnel issues Use of equip/system - Pilot

Aircraft Gear extension and retract sys - Not used/operated

# **Factual Information**

# History of Flight

Landing	Landing gear not configured (Defining event)	
Landing-landing roll	Runway excursion	

# Pilot Information

Certificate:	Commercial	Age:	0,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	Helicopter	Restraint Used:	Lap only
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	BasicMed Without waivers/limitations	Last FAA Medical Exam:	June 25, 2021
Occupational Pilot:	No	Last Flight Review or Equivalent:	July 5, 2021
Flight Time:	1044.5 hours (Total, all aircraft), 6.7 hours (Total, this make and model), 943.8 hours (Pilot In Command, all aircraft), 1.4 hours (Last 90 days, all aircraft), 1.4 hours (Last 30 days, all aircraft), 1.4 hours (Last 24 hours, all aircraft)		

# **Aircraft and Owner/Operator Information**

Aircraft Make:	Beech	Registration:	N4210D
Model/Series:	G35	Aircraft Category:	Airplane
Year of Manufacture:	1956	Amateur Built:	
Airworthiness Certificate:	Utility	Serial Number:	D-4415
Landing Gear Type:	Retractable - Tricycle	Seats:	4
Date/Type of Last Inspection:	October 27, 2021 Annual	Certified Max Gross Wt.:	2975 lbs
Time Since Last Inspection:	4.6 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	6615 Hrs as of last inspection	Engine Manufacturer:	Continental
ELT:	C91 installed, not activated	Engine Model/Series:	E-225-8
Registered Owner:	On file	Rated Power:	225 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Page 2 of 4 CEN23LA116

# Meteorological Information and Flight Plan

# **Airport Information**

Airport:	Grand Prairie Municipal GPM	Runway Surface Type:	Concrete
Airport Elevation:	590 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	18	IFR Approach:	None
Runway Length/Width:	4001 ft / 75 ft	VFR Approach/Landing:	Full stop

# Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	32.69,-97.04

Page 3 of 4 CEN23LA116

#### **Administrative Information**

Investigator In Charge (IIC): Abraham, Laura

Additional Participating Persons:

Original Publish Date: July 27, 2023

Last Revision Date:

Investigation Class: Class 4

Note: The NTSB did not travel to the scene of this accident.

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=106764

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 CEN23LA116