



Aviation Investigation Final Report

Location: Oklahoma City, Oklahoma Accident Number: CEN23LA140

Date & Time: March 19, 2023, 13:14 Local Registration: N9254A

Aircraft: Cessna 170A Aircraft Damage: Substantial

Defining Event: Loss of control on ground **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot reported that after touchdown on the runway, a gust of wind pushed the tail of the airplane to the left. The pilot was unable to maintain directional control and the airplane departed the runway and nosed over in a grassy area adjacent to the runway. The airplane sustained substantial damage to the left wing. The pilot reported that there were no preaccident mechanical malfunctions or failures that would have precluded normal operation. The reported winds about the time of the accident were light and variable at 3 knots.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's loss of directional control during landing with wind gusts, which resulted in a runway excursion and nose over.

Findings

Personnel issues (general) - Pilot

Environmental issues Gusts - Contributed to outcome

Page 2 of 5 CEN23LA140

Factual Information

History of Flight

Landing-flare/touchdown Loss of control on ground (Defining event)
--

Pilot Information

Certificate:	Private	Age:	72,Male
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Unknown
Instrument Rating(s):	None	Second Pilot Present:	
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	BasicMed Without waivers/limitations	Last FAA Medical Exam:	July 25, 2022
Occupational Pilot:	No	Last Flight Review or Equivalent:	September 15, 2022
Flight Time:	1360 hours (Total, all aircraft), 36 hours (Total, this make and model), 15 hours (Last 90 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N9254A
Model/Series:	170A NO SERIES	Aircraft Category:	Airplane
Year of Manufacture:	1949	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	19015
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	March 8, 2023 Annual	Certified Max Gross Wt.:	2200 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	5804.7 Hrs at time of accident	Engine Manufacturer:	Continental
ELT:	C91 installed, not activated	Engine Model/Series:	O-300A
Registered Owner:	FARNSLEY AERO LLC	Rated Power:	145 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None
Operator Does Business As:	Co-Owner	Operator Designator Code:	

Page 3 of 5 CEN23LA140

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KPWA,1280 ft msl	Distance from Accident Site:	6 Nautical Miles
Observation Time:	12:53 Local	Direction from Accident Site:	300°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	None / None
Wind Direction:		Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	30.5 inches Hg	Temperature/Dew Point:	5°C / -13°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	Oklahoma City, OK	Type of Flight Plan Filed:	None
Destination:	Oklahoma City, OK	Type of Clearance:	None
Departure Time:		Type of Airspace:	Class C

Airport Information

Airport:	Wiley Post KPWA	Runway Surface Type:	Concrete
Airport Elevation:	1310 ft msl	Runway Surface Condition:	Dry
Runway Used:	35R	IFR Approach:	None
Runway Length/Width:	7199 ft / 150 ft	VFR Approach/Landing:	Full stop;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	35.491476,-97.540528(est)

Page 4 of 5 CEN23LA140

Administrative Information

Investigator In Charge (IIC): Lemishko, Alexander

Additional Participating Persons:

Original Publish Date: June 23, 2023

Last Revision Date:

Investigation Class: Class 4

Note: The NTSB did not travel to the scene of this accident.

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=106910

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 CEN23LA140