



# **Aviation Investigation Final Report**

Location: Reidsville, North Carolina Accident Number: ERA23LA244

Date & Time: May 23, 2023, 12:45 Local Registration: N8992J

Aircraft: Piper PA28 Aircraft Damage: Substantial

**Defining Event:** Loss of control on ground **Injuries:** 1 Minor

Flight Conducted Under: Part 91: General aviation - Instructional

#### **Analysis**

The solo student pilot described that, during the landing approach, there was a crosswind from the right. When the airplane touched down, it drifted to the left. The pilot attempted to correct by applying right rudder, but the airplane departed the left side of the runway and continued through a ditch, resulting in substantial damage to the empennage. The pilot reported that there were no preimpact mechanical malfunctions or failures of the airplane that would have precluded normal operation.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain directional control of the airplane while landing in a crosswind.

#### **Findings**

Personnel issues Aircraft control - Pilot

Aircraft Directional control - Not attained/maintained

Environmental issues Crosswind - Response/compensation

## **Factual Information**

## History of Flight

Landing	Loss of control on ground (Defining event)	
Landing-landing roll	Runway excursion	

#### **Pilot Information**

Certificate:	Sport Pilot	Age:	28,Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Unknown
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	September 29, 2022
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	47 hours (Total, all aircraft), 47 hours (Total, this make and model), 5.1 hours (Pilot In Command, all aircraft), 14 hours (Last 90 days, all aircraft), 5.7 hours (Last 30 days, all aircraft), 2.1 hours (Last 24 hours, all aircraft)		

### **Aircraft and Owner/Operator Information**

Aircraft Makes	Dinor	Domintuntions	NICOCOL
Aircraft Make:	Piper	Registration:	N8992J
Model/Series:	PA28 180	Aircraft Category:	Airplane
Year of Manufacture:	1965	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	28-3016
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	May 3, 2023 100 hour	Certified Max Gross Wt.:	
Time Since Last Inspection:	80 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	6430 Hrs at time of accident	Engine Manufacturer:	Lycoming
ELT:		Engine Model/Series:	0-360
Registered Owner:	On file	Rated Power:	180
Operator:	On file	Operating Certificate(s) Held:	None

Page 2 of 4 ERA23LA244

## Meteorological Information and Flight Plan

Visual (VMC)	Condition of Light:	Day
KSIF,693 ft msl	Distance from Accident Site:	0 Nautical Miles
12:45 Local	Direction from Accident Site:	136°
Clear	Visibility	10 miles
None	Visibility (RVR):	
6 knots /	Turbulence Type Forecast/Actual:	/
80°	Turbulence Severity Forecast/Actual:	/
30.21 inches Hg	Temperature/Dew Point:	22°C / 9°C
No Obscuration; No Precipitation		
Hickory, NC (HKY)	Type of Flight Plan Filed:	None
Reidsville, NC	Type of Clearance:	None
12:00 Local	Type of Airspace:	Class G
	KSIF,693 ft msl  12:45 Local  Clear  None 6 knots /  80°  30.21 inches Hg  No Obscuration; No Precipitate Hickory, NC (HKY)  Reidsville, NC	KSIF,693 ft msl Distance from Accident Site:  12:45 Local Direction from Accident Site:  Clear Visibility None Visibility (RVR):  6 knots / Turbulence Type Forecast/Actual:  80° Turbulence Severity Forecast/Actual:  30.21 inches Hg Temperature/Dew Point:  No Obscuration; No Precipitation Hickory, NC (HKY) Type of Flight Plan Filed:  Reidsville, NC Type of Clearance:

## **Airport Information**

Airport:	Rockingham County SIF	Runway Surface Type:	Asphalt
Airport Elevation:	693 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	13	IFR Approach:	None
Runway Length/Width:	5200 ft / 100 ft	VFR Approach/Landing:	Touch and go;Traffic pattern

### **Wreckage and Impact Information**

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	36.438941,-79.853334(est)

Page 3 of 4 ERA23LA244

#### **Administrative Information**

Investigator In Charge (IIC):	Diaz, Dennis
Additional Participating Persons:	Richard A. Brown; FAA/FSDO; Portland, ME
Original Publish Date:	July 7, 2023
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=192236

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 ERA23LA244