



Aviation Investigation Final Report

Location: Point Thomson, Alaska Accident Number: ANC23LA036

Date & Time: May 17, 2023, 12:22 Local Registration: N34WM

Aircraft: Piper PA31 Aircraft Damage: Substantial

Defining Event: Controlled flight into terr/obj (CFIT) **Injuries:** 2 None

Flight Conducted Under: Part 135: Air taxi & commuter - Non-scheduled

Analysis

The pilot reported that while established on an RNAV GPS instrument approach to a remote airport, flat light conditions made it difficult to decern topographical features of the snow-covered terrain below. Prior to reaching the decision height altitude, the pilot said he looked outside for the runway environment, but the flat light condition caused him to spend more time looking outside and he became disorientated. When he looked back at the airplane's instruments, he noticed the airplane was below the glide path and initiated a go-around maneuver; however, the airplane subsequently impacted snow-covered terrain. The pilot reported that there were no preaccident mechanical malfunctions or failures with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's inadvertent descent below the published minimum descent altitude, while operating in flat light conditions, which resulted in controlled flight into terrain.

Findings

Personnel issues Aircraft control - Pilot

Personnel issues Task monitoring/vigilance - Pilot

Environmental issues Flat light - Contributed to outcome

Environmental issues Snowy/icy terrain - Contributed to outcome

Aircraft Descent/approach/glide path - Not attained/maintained

Page 2 of 6 ANC23LA036

Factual Information

History of Flight

Approach-IFR final approach	Controlled flight into terr/obj (CFIT) (Defining event)	
Approach-IFR final approach	Loss of visual reference	

Pilot Information

Certificate:	Commercial	Age:	30,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane single-engine	Toxicology Performed:	
Medical Certification:	Class 1 With waivers/limitations	Last FAA Medical Exam:	May 3, 2023
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	November 6, 2022
Flight Time:	1636 hours (Total, all aircraft), 89 hours (Total, this make and model), 1558 hours (Pilot In Command, all aircraft), 110 hours (Last 90 days, all aircraft), 45 hours (Last 30 days, all aircraft), 5 hours (Last 24 hours, all aircraft)		

Pilot-rated passenger Information

Certificate:	Airline transport; Commercial	Age:	47,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 2 With waivers/limitations	Last FAA Medical Exam:	March 8, 2023
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	7145 hours (Total, all aircraft)		

Page 3 of 6 ANC23LA036

Aircraft and Owner/Operator Information

Aircraft Make:	Piper	Registration:	N34WM
Model/Series:	PA31 350	Aircraft Category:	Airplane
Year of Manufacture:	1973	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	31-7305125
Landing Gear Type:	Retractable - Tricycle	Seats:	5
Date/Type of Last Inspection:	May 8, 2023 AAIP	Certified Max Gross Wt.:	7368 lbs
Time Since Last Inspection:		Engines:	2 Reciprocating
Airframe Total Time:	19217 Hrs at time of accident	Engine Manufacturer:	Lycoming
ELT:	C126 installed, activated, did not aid in locating accident	Engine Model/Series:	TIO-540-J2B
Registered Owner:	70 NORTH LLC	Rated Power:	360 Horsepower
Operator:	JuniPogo LLC	Operating Certificate(s) Held:	On-demand air taxi (135)
Operator Does Business As:	70 North	Operator Designator Code:	3JPA

Meteorological Information and Flight Plan

meteorological informati	on the same		
Conditions at Accident Site:	Instrument (IMC)	Condition of Light:	Day
Observation Facility, Elevation:	PASC,58 ft msl	Distance from Accident Site:	45 Nautical Miles
Observation Time:	12:18 Local	Direction from Accident Site:	275°
Lowest Cloud Condition:	Few / 500 ft AGL	Visibility	1 miles
Lowest Ceiling:	Broken / 1500 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	6 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	60°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.21 inches Hg	Temperature/Dew Point:	-3°C / -5°C
Precipitation and Obscuration:	Moderate - None - Mist		
Departure Point:	Deadhorse, AK (PASC)	Type of Flight Plan Filed:	IFR
Destination:	Point Thomson, AK	Type of Clearance:	IFR
Departure Time:	12:04 Local	Type of Airspace:	Class G

Page 4 of 6 ANC23LA036

Airport Information

Airport:	POINT THOMSON AIRSTRIP 37AA	Runway Surface Type:	
Airport Elevation:	56 ft msl	Runway Surface Condition:	Snow
Runway Used:		IFR Approach:	RNAV
Runway Length/Width:		VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	70.136,-146.29002(est)

Page 5 of 6 ANC23LA036

Administrative Information

Investigator In Charge (IIC):	Hill, Millicent
Additional Participating Persons:	James Howery; FAA/FSDO; Anchorage, AK
Original Publish Date:	October 20, 2023
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=192218

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ANC23LA036