



Aviation Investigation Final Report

Location: Limon, Colorado Accident Number: CEN23LA102

Date & Time: February 1, 2023, 16:00 Local Registration: N5163H

Aircraft: Cessna 172S Aircraft Damage: Substantial

Defining Event: Loss of control on ground **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Instructional

Analysis

The student pilot reported that he was performing touch-and-go landings. When he added power to take off, he lost control of the airplane as it veered left. He was unable to regain control before the airplane impacted a snowbank. The airplane flipped over and came to rest inverted on the side of the runway, which resulted in substantial damage to the wings, fuselage, and vertical stabilizer. The pilot reported there were no mechanical malfunctions or failures that would have precluded normal operations. At the time of the accident, the pilot was landing on Runway 34 with wind from 350°at 4 knots.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain directional control during the takeoff roll.

Findings

Personnel issues Aircraft control - Pilot

Aircraft Directional control - Not attained/maintained

Factual Information

History of Flight

| Takeoff | Loss of control on ground (Defining event) |
|---------|--|
| Takeoff | Runway excursion |
| Takeoff | Nose over/nose down |

Pilot Information

| Certificate: | Student | Age: | 23,Male |
|---------------------------|---|---|--------------------------|
| Airplane Rating(s): | None | Seat Occupied: | Left |
| Other Aircraft Rating(s): | None | Restraint Used: | |
| Instrument Rating(s): | None | Second Pilot Present: | No |
| Instructor Rating(s): | None | Toxicology Performed: | |
| Medical Certification: | Class 1 With waivers/limitations | Last FAA Medical Exam: | June 1, 2021 |
| Occupational Pilot: | No | Last Flight Review or Equivalent: | |
| Flight Time: | 99 hours (Total, all aircraft), 99 hour aircraft) | rs (Total, this make and model), 14.1 h | nours (Last 90 days, all |

Aircraft and Owner/Operator Information

| Aircraft Make: | Cessna | Registration: | N5163H |
|-------------------------------|-------------|-----------------------------------|----------|
| Model/Series: | 172S | Aircraft Category: | Airplane |
| Year of Manufacture: | 2001 | Amateur Built: | |
| Airworthiness Certificate: | Normal | Serial Number: | 172S8933 |
| Landing Gear Type: | | Seats: | 4 |
| Date/Type of Last Inspection: | | Certified Max Gross Wt.: | |
| Time Since Last Inspection: | | Engines: | 1 |
| Airframe Total Time: | | Engine Manufacturer: | |
| ELT: | | Engine Model/Series: | |
| Registered Owner: | EDB Air Inc | Rated Power: | |
| Operator: | EDB Air Inc | Operating Certificate(s) Held: | None |
| | | | |

Page 2 of 4 CEN23LA102

Meteorological Information and Flight Plan

| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Day |
|----------------------------------|----------------------------------|--------------------------------------|------------------|
| Observation Facility, Elevation: | KLIC,5358 ft msl | Distance from Accident Site: | 0 Nautical Miles |
| Observation Time: | 15:55 Local | Direction from Accident Site: | 331° |
| Lowest Cloud Condition: | Clear | Visibility | 10 miles |
| Lowest Ceiling: | None | Visibility (RVR): | |
| Wind Speed/Gusts: | 4 knots / | Turbulence Type Forecast/Actual: | / |
| Wind Direction: | 350° | Turbulence Severity Forecast/Actual: | / |
| Altimeter Setting: | 30.09 inches Hg | Temperature/Dew Point: | -3°C / -9°C |
| Precipitation and Obscuration: | No Obscuration; No Precipitation | | |
| Departure Point: | Limon, CO | Type of Flight Plan Filed: | None |
| Destination: | Limon, CO | Type of Clearance: | VFR |
| Departure Time: | | Type of Airspace: | Class G |
| | | | |

Airport Information

| Airport: | Limon Municipal KLIC | Runway Surface Type: | Asphalt |
|----------------------|----------------------|----------------------------------|--------------|
| Airport Elevation: | 5374 ft msl | Runway Surface Condition: | Dry |
| Runway Used: | 34 | IFR Approach: | Unknown |
| Runway Length/Width: | 4700 ft / 60 ft | VFR Approach/Landing: | Touch and go |

Wreckage and Impact Information

| Crew Injuries: | 1 None | Aircraft Damage: | Substantial |
|------------------------|--------|-------------------------|----------------------|
| Passenger Injuries: | N/A | Aircraft Fire: | None |
| Ground Injuries: | | Aircraft Explosion: | None |
| Total Injuries: | 1 None | Latitude, Longitude: | 39.269236,-103.66428 |

Page 3 of 4 CEN23LA102

Administrative Information

Investigator In Charge (IIC): Abraham, Laura

Additional Participating Persons:

Original Publish Date: June 6, 2023

Last Revision Date:

Investigation Class: Class 4

Note: The NTSB did not travel to the scene of this accident.

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=106688

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 CEN23LA102