



Aviation Investigation Final Report

Location: Princeton, Minnesota Accident Number: CEN23LA122

Date & Time: February 25, 2023, 15:00 Local Registration: N208SP

Aircraft: Cessna 172S Aircraft Damage: Substantial

Defining Event: Loss of control on ground **Injuries:** 3 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot reported that during takeoff the airplane "started to slide to the left on the ice" on the snow and ice-covered runway. The pilot chose to abort the takeoff. During the abort, the airplane kept "pulling to the left" and impacted the terrain between the runway and taxiway. Upon impact, the airplane nosed over which resulted in substantial damage to the fuselage, wings, and wing struts. At the time of the accident, the pilot was taking off with a 40° right crosswind at 8 knots.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain directional control during the takeoff roll. Contributing to the accident, was the runway condition combined with a right crosswind.

Findings

Personnel issues Aircraft control - Pilot

Environmental issues Snow/slush/ice covered surface - Effect on operation

Environmental issues Crosswind - Effect on operation

Page 2 of 6 CEN23LA122

Factual Information

History of Flight

Takeoff-rejected takeoff	Loss of control on ground (Defining event)
Takeoff	Nose over/nose down

Pilot Information

Certificate:	Private	Age:	44,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Unknown
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	August 3, 2021
Occupational Pilot:	No	Last Flight Review or Equivalent:	January 30, 2023
Flight Time:	(Estimated) 103 hours (Total, all aircraft), 103 hours (Total, this make and model), 30 hours (Pilot In Command, all aircraft), 17 hours (Last 90 days, all aircraft), 7 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Passenger Information

Certificate:	Age:	
Airplane Rating(s):	Seat Occupied:	Right
Other Aircraft Rating(s):	Restraint Used:	3-point
Instrument Rating(s):	Second Pilot Present:	No
Instructor Rating(s):	Toxicology Performed:	
Medical Certification:	Last FAA Medical Exam:	
Occupational Pilot:	Last Flight Review or Equivale	nt:
Flight Time:		

Page 3 of 6 CEN23LA122

Passenger Information

Certificate:	Age:	
Airplane Rating(s):	Seat Occupied:	Rear
Other Aircraft Rating(s):	Restraint Used:	3-point
Instrument Rating(s):	Second Pilot Present:	No
Instructor Rating(s):	Toxicology Performed:	
Medical Certification:	Last FAA Medical Exam:	
Occupational Pilot:	Last Flight Review or Equivalent:	
Flight Time:		

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N208SP
Model/Series:	172S	Aircraft Category:	Airplane
Year of Manufacture:	1999	Amateur Built:	
Airworthiness Certificate:	Normal; Utility	Serial Number:	172S8208
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	February 17, 2023 Annual	Certified Max Gross Wt.:	2550 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	10851 Hrs as of last inspection	Engine Manufacturer:	Lycoming
ELT:	C126 installed, activated, aided in locating accident	Engine Model/Series:	IO-360-L2A
Registered Owner:	208SP LLC	Rated Power:	180
Operator:	Twin Cities Flight Training, Inc	Operating Certificate(s) Held:	None

Page 4 of 6 CEN23LA122

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KPNM,979 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	14:55 Local	Direction from Accident Site:	101°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	8 knots /	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	200°	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	29.96 inches Hg	Temperature/Dew Point:	-6°C / -12°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Princeton, MN	Type of Flight Plan Filed:	None
Destination:	Blaine, MN (KANE)	Type of Clearance:	None
Departure Time:		Type of Airspace:	Class G

Airport Information

Airport:	Princeton Municipal Airport PNM	Runway Surface Type:	Asphalt
Airport Elevation:	980 ft msl	Runway Surface Condition:	Dry;lce;Snow
Runway Used:	16	IFR Approach:	None
Runway Length/Width:	3900 ft / 75 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	2 None	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	3 None	Latitude, Longitude:	45.56005,-93.608366(est)

Page 5 of 6 CEN23LA122

Administrative Information

Investigator In Charge (IIC):	Finne, Andrew
Additional Participating Persons:	Thurston, Greg; FAA - FSDO; Minneapolis, MN
Original Publish Date:	March 30, 2023
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=106790

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 CEN23LA122