



Aviation Investigation Final Report

Location: Orangeburg, South Carolina Accident Number: ERA24LA021

Date & Time: October 21, 2023, 13:00 Local Registration: N7607T

Aircraft: Cessna 172 Aircraft Damage: Substantial

Defining Event: Collision with terr/obj (non-CFIT) **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Instructional

Analysis

The flight instructor and the student pilot were practicing crosswind takeoffs and landings. After completing two successful landings, the student pilot was taxiing back to the runway when the airplane drifted to the right and the right wing impacted a fuel truck parked next to the taxiway. The impact resulted in substantial damage to the right wing. The flight instructor reported that there were no preaccident mechanical malfunctions or failures with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The student pilot's failure to maintain adequate clearance from a fuel truck while taxiing. Also contributing was the flight instructor's inadequate monitoring of the student pilot.

Findings

Personnel issues Identification/recognition - Student/instructed pilot

Personnel issues Monitoring environment - Instructor/check pilot

Environmental issues Ground vehicle - Awareness of condition

Page 2 of 6 ERA24LA021

Factual Information

History of Flight

Taxi-to runway	Collision with terr/obj (non-CFIT) (Defining event)	
----------------	---	--

Flight instructor Information

Certificate:	Commercial; Flight instructor	Age:	81.Male
Gertificate.	Commercial, ringht instructor	Age.	O I,IVICIE
Airplane Rating(s):	Single-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	None	Restraint Used:	Lap only
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane single-engine	Toxicology Performed:	
Medical Certification:	Class 2 With waivers/limitations	Last FAA Medical Exam:	August 17, 2023
Occupational Pilot:	No	Last Flight Review or Equivalent:	December 26, 2022
Flight Time:	4371 hours (Total, all aircraft), 1200 hours (Total, this make and model), 4350 hours (Pilot In Command, all aircraft), 35 hours (Last 90 days, all aircraft), 4 hours (Last 30 days, all aircraft), 0 hours (Last 24 hours, all aircraft)		

Student pilot Information

Certificate:	None	Age:	62,Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Lap only
Instrument Rating(s):	None	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	May 3, 2023
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	23 hours (Total, all aircraft), 23 hours (Total, this make and model), 23 hours (Last 90 days, all aircraft), 9 hours (Last 30 days, all aircraft)		

Page 3 of 6 ERA24LA021

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N7607T
Model/Series:	172 A	Aircraft Category:	Airplane
Year of Manufacture:	1959	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	47207
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	April 1, 2023 Annual	Certified Max Gross Wt.:	2200 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	3576.6 Hrs at time of accident	Engine Manufacturer:	CONTINENTAL MOTORS
ELT:	Installed, not activated	Engine Model/Series:	0-300
Registered Owner:	On file	Rated Power:	145 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	OGB,194 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	12:53 Local	Direction from Accident Site:	90°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	7 knots / 17 knots	Turbulence Type Forecast/Actual:	Unknown / Terrain- Induced
Wind Direction:	300°	Turbulence Severity Forecast/Actual:	Unknown / Light
Altimeter Setting:	29.82 inches Hg	Temperature/Dew Point:	22°C / 5°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Orangeburg, SC	Type of Flight Plan Filed:	None
Destination:	Orangeburg, SC	Type of Clearance:	None
Departure Time:		Type of Airspace:	Class G

Page 4 of 6 ERA24LA021

Airport Information

Airport:	ORANGEBURG MUNI OGB	Runway Surface Type:	Asphalt
Airport Elevation:	195 ft msl	Runway Surface Condition:	Dry
Runway Used:	23	IFR Approach:	None
Runway Length/Width:	4508 ft / 100 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	33.464015,-80.856435(est)

Page 5 of 6 ERA24LA021

Administrative Information

Investigator In Charge (IIC):	Young, Joshua
Additional Participating Persons:	Jeffery Kimbrell; FAA/FSDO; Columbia, SC
Original Publish Date:	November 16, 2023
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=193303

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ERA24LA021