



Aviation Investigation Final Report

Location: Greensboro, North Carolina Accident Number: ERA24LA133

Date & Time: March 8, 2024, 11:55 Local Registration: N8455R

Aircraft: Piper PA28 Aircraft Damage: Substantial

Defining Event: Loss of control on ground **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The student pilot was landing with a crosswind. He stated that after the main landing gear touched down, a gust of wind pushed the airplane to the right. After the nosewheel touched down, the airplane was pointed toward the runway's precision approach path indicator lights. The airplane subsequently travelled off the right side of the runway and struck two of the lights. Both of the airplane's wings were substantially damaged. The pilot reported that there were no preimpact mechanical malfunctions or failures of the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain directional control while landing with a crosswind.

Findings

Aircraft Directional control - Not attained/maintained

Personnel issues Aircraft control - Pilot

Environmental issues Crosswind - Response/compensation

Page 2 of 5 ERA24LA133

Factual Information

History of Flight

Landing-landing roll	Loss of control on ground (Defining event)	
Landing-landing roll	Runway excursion	

Student pilot Information

Certificate:	Student	Age:	Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 1 Without waivers/limitations	Last FAA Medical Exam:	December 8, 2023
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	56 hours (Total, all aircraft), 56 hours (Total, this make and model), 6 hours (Pilot In Command, all aircraft), 56 hours (Last 90 days, all aircraft), 17 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Piper	Registration:	N8455R
All Clait Wake.	ripei	Registration.	11045511
Model/Series:	PA28 140	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	28-22356
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	February 21, 2024 100 hour	Certified Max Gross Wt.:	2150 lbs
Time Since Last Inspection:	40 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	5170 Hrs at time of accident	Engine Manufacturer:	Lycoming
ELT:	Installed, not activated	Engine Model/Series:	0-320-E2A
Registered Owner:	Skyways Group LLC	Rated Power:	140
Operator:	On file	Operating Certificate(s) Held:	None

Page 3 of 5 ERA24LA133

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	GS0,886 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	11:54 Local	Direction from Accident Site:	253°
Lowest Cloud Condition:	Few / 3000 ft AGL	Visibility	10 miles
Lowest Ceiling:	Overcast / 3700 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	8 knots /	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	140°	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	30.19 inches Hg	Temperature/Dew Point:	16°C / 7°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	South Boston, VA (W78)	Type of Flight Plan Filed:	None
Destination:	Greensboro, NC	Type of Clearance:	None
Departure Time:	11:00 Local	Type of Airspace:	Class C

Airport Information

Airport:	PIEDMONT TRIAD INTL GSO	Runway Surface Type:	Asphalt
Airport Elevation:	925 ft msl	Runway Surface Condition:	Dry
Runway Used:	05	IFR Approach:	None
Runway Length/Width:	9000 ft / 150 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	36.099251,-79.933604

Page 4 of 5 ERA24LA133

Administrative Information

Boggs, Daniel	
Patricia Chriscoe; FAA/FSDO; Greensboro, NC	
May 3, 2024	
Class 4	
The NTSB did not travel to the scene of this accident.	
https://data.ntsb.gov/Docket?ProjectID=193900	
,	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 ERA24LA133