



Aviation Investigation Final Report

Location: Anderson, South Carolina Accident Number: ERA23LA391

Date & Time: September 3, 2023, 09:30 Local Registration: N192HH

Aircraft: Balloon Works Firefly 7 Aircraft Damage: Substantial

Defining Event: Collision with terr/obj (non-CFIT) **Injuries:** 1 Minor, 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot of the balloon reported that before the flight, the reported wind direction called for a favorable path with many available landing areas; however, during the flight the wind shifted and the balloon traveled over congested living areas and neighborhoods. As he was looking for a place to land the wind was light and variable. He attempted an approach to a cul-de-sac; however, spectators were parked there, preventing a landing. He aborted the approach and tried another to a corner field. That approach was also aborted due to powerlines in the vicinity. He attempted another approach to a "small area" and the balloon's envelope caught tree limbs during the descent. After becoming briefly suspended in the tree branches about 5 to 8 feet above the ground, the branches broke and balloon basket dropped to the ground. The passenger sustained a minor injury, the pilot was not injured. Postaccident examination of the balloon revealed substantial damage to several fabric panels and two suspension cables. The pilot reported that there were no preaccident mechanical malfunctions or failures with the balloon that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to avoid trees during the descent for landing, resulting in substantial damage to the balloon.

Findings

Personnel issues Decision making/judgment - Pilot

Aircraft Descent/approach/glide path - Not attained/maintained

Environmental issues Tree(s) - Response/compensation

Page 2 of 5 ERA23LA391

Factual Information

History of Flight

Landing Collision with terr/obj (non-CFIT) (Defining event)

Pilot Information

Certificate:	Commercial	Age:	55,Male
Airplane Rating(s):	None	Seat Occupied:	None
Other Aircraft Rating(s):	Balloon; Helicopter	Restraint Used:	
Instrument Rating(s):	Helicopter	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 2 With waivers/limitations	Last FAA Medical Exam:	April 18, 2023
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	August 10, 2023
Flight Time:	4500 hours (Total, all aircraft), 127 hours (Total, this make and model), 3800 hours (Pilot In Command, all aircraft), 65 hours (Last 90 days, all aircraft), 20 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Balloon Works	Registration:	N192HH
Model/Series:	Firefly 7 15	Aircraft Category:	Balloon
Year of Manufacture:	1992	Amateur Built:	
Airworthiness Certificate:	Balloon	Serial Number:	F7-781
Landing Gear Type:	None	Seats:	
Date/Type of Last Inspection:	May 4, 2023 Annual	Certified Max Gross Wt.:	
Time Since Last Inspection:		Engines:	0
Airframe Total Time:	286 Hrs at time of accident	Engine Manufacturer:	
ELT:	Not installed	Engine Model/Series:	
Registered Owner:	On file	Rated Power:	
Operator:	On file	Operating Certificate(s) Held:	None

Page 3 of 5 ERA23LA391

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KAND,773 ft msl	Distance from Accident Site:	2 Nautical Miles
Observation Time:	09:56 Local	Direction from Accident Site:	240°
Lowest Cloud Condition:	Clear	Visibility	
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	None / None
Wind Direction:		Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	30.17 inches Hg	Temperature/Dew Point:	24°C / 19°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	Anderson, SC	Type of Flight Plan Filed:	None
Destination:	Anderson, SC	Type of Clearance:	None
Departure Time:		Type of Airspace:	Class G

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 Minor	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 Minor, 1 None	Latitude, Longitude:	34.51806,-82.67222(est)

Page 4 of 5 ERA23LA391

Administrative Information

Investigator In Charge (IIC):	Hicks, Ralph
Additional Participating Persons:	Daryl McMillan; FAA/FSDO; Columbia, SC
Original Publish Date:	January 25, 2024
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=193306

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 ERA23LA391