




Fig. 2 — Scarfing and drilling for single intermediate and section poles