

FOC CALL DETAILS PAGE

Tracking No :-	824Q00001	Customer Name :-	SAIDHAM SUPER SERVICES PVT LTD
Foc no :-	8241AP100	Foc Type :-	WARRANTY FAILURE FOC
Foc Date :-	26.06.2026 13:20	Branch :-	
OEM :-	OD GOVT	Dealer Name & Address :-	CRS000229
Mode of Dispatch :-	AIR_Frieght	Delivery Address :-	SAMBEET EQUIPMENTS PRIVATE LIMITED 590/1019, ROOM NO. 3,1ST FLOOR CUTTACK - 753012 CUTTACK OR IND 753012
Concerned Dealer :-	Sambeet equipments private limited	Total Foc Value :-	160460
product :-	TWBT - 11	fab no :-	250201901003
FIR No. :-	824Q00001B	Logged Date & Time :-	26.06.2026 13:20
Sale Date :-	30.12.2025	Comm Date :-	28.04.2026
Dt of failure :-	24.04.2026	Clocked Hours :-	1
Working Hours/Day :-	1	Load/unload :-	nil-nil
Failure Nature :-	Commissioning	Field Inference :-	Loadcell is not working for two-wheeler brake tester

FOC ATTACHMENTS

[FOC85701-FOC.pdf](#)

LIST OF PARTS USED / REQUIRED

sl NO.	Item Code	Description	FOC Recommended	Used Qty	Required Qty	Price Type	Item Price	Part Value
1	890405110	FORCE CELL CF200-TWB11	YES	0	4	CC-PRICE	40115	160460

Logged By :-

ABHIJIT NANDA

RCA Reference No

0

CORRECTIVE ACTION
RECOMParts bring to HO for
analyze

Approvers Detail

DOMESTIC

	AREA MANAGER	COORDINATOR	HO PRODUCT MANAGER	HEAD AFTER SALES	QUALITY	MANAGING DIRECTOR	MANAGING DIRECTOR
APPROVER NAME	ATANU AJIT SAHA	HARI PRASATH G	ALAGU SUNDAR	SURESH.K			
APPROVED DATE	26.06.2026 16:50	26.06.2026 17:07	30.06.2026 12:19	30.06.2026 12:42			

APPROVER COMM	Pls proces		Premature Failure. (As per Engineer problem found on loadcell not in board. Previous supplied board not used and will be returned to HO.)	Since 2wh lane is new, we took advise from VTEQ. Initially it was suggested to go for Electronic PCB. Then they advised to replace the Sensor. PCB will be taken back through SRN			
------------------	------------	--	--	--	--	--	--

Copyright © Elgi Equipments Ltd, Singanallur. All rights reserved.