Revision 5

Page: 48

BALI INTERNATIONAL FLIGHT ACADEMY

Effective: Jun. 2021

Mission 48

CPL MANEUVERS - SUPERVISED PIC

| STUDENT: FAJAR SAMUDERA | DATE 1: 12/5/2022 | DATE 2: | |
|-------------------------|-------------------|-----------|--|
| INSTRUCTOR: CAPT THESAR | A/C REG: PK ROZ | A/C REG: | |
| A/C TYPE: Cl72 | DURATION: 1-30 | DURATION: | |

| | Exercises | 1 | 2 | COMMENTS: |
|----|-----------------------------------|---|---|------------------|
| R- | Pre-Flight Inspection | 9 | | A.L. Is |
| R- | Required Documents Inspection | 5 | | 4 landing |
| R- | Checklist Usage | 5 | | |
| R- | Short Field Take-Off | 2 | | 1 low circuit |
| R- | Departure to Training Area | 9 | | 1.001 |
| | | | | IPFL |
| R- | Pre-Manoeuvre Checks | 5 | | |
| R- | Power Off Clean Stall - Full | 8 | | |
| R- | Power Off Clean Stall - Incipient | 2 | | |
| R- | Power Off Dirty Stall - Full | 5 | | |
| R- | Power Off Dirty Stall - Incipient | 2 | | |
| R- | Power On Clean Stall - Incipient | 5 | | |
| R- | Power On Dirty Stall - Incipient | 5 | | |
| R- | Steep Turns | ç | | |
| R- | Slow Flight | 5 | | |
| | 4 | | | |
| R- | Alternator Failure | 5 | | |
| R- | Engine Fire in Flight / PFL | 2 | | |
| R- | Engine Failure After Take-Off | 1 | | |
| R- | Flapless Landing | 2 | | |
| R- | Short Field Landing | 5 | | |
| R- | Low Level Circuits | 5 | | |
| | | | | |
| | | | | |
| | | | | |
| | 4 | | | LILES CONTRACTOR |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

COMPLETION STANDARDS:

Able to maintain altitude ± 50 ft., heading ± 10°, airspeed ± 5 kts. and bank angle ± 5° for all exercises.

SYLLABUS TIMES:

| Total | Dual | PIC | X/C | IF | Ldgs | Night |
|-------|------|------|-----|----|------|-------|
| 84:00 | | 1:30 | | | 4 | |
| | | 1:30 | | | 4 | |

Student Signature

Instructor Signature