National Transportation Safety Board
Aviation Accident Final Report

Location:	Bridgeport, TX	**Accident Number:**	DFW08CA041
Date & Time:	11/28/2007, 1515 CST	**Registration:**	N64197
Aircraft:	Cessna 172P	**Aircraft Damage:**	Substantial
Defining Event:		**Injuries:**	1 None
Flight Conducted Under:	Part 91: General Aviation - Personal		

Analysis

The 47-hour private pilot was executing full stop landing on Runway 17 with the wind reported from 230 degrees at 9 knots. During the landing flare, the airplane drifted left of the runway centerline, and the pilot corrected by applying crosswind controls and continued the landing. The airplane touched down with the left main landing gear off of the 60-foot wide runway and the pilot lost directional control of the airplane. The nose landing gear buckled, the airplane nosed-over, coming to rest in the inverted position. The pilot was not wearing the installed shoulder harness and egressed the airplane with minor injuries. The operator of the airplane recommended that a go-around would have prevented this accident.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's failure to maintain direction control of the airplane while landing with a crosswind. A contributing factor was the prevailing crosswind.

Findings

Occurrence #1: LOSS OF CONTROL - IN FLIGHT
Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings
1. (F) WEATHER CONDITION - CROSSWIND
2. CROSSWIND COMPONENT - NOT CORRECTED - PILOT IN COMMAND
3. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

Occurrence #2: NOSE OVER
Phase of Operation: LANDING

Findings
4. LANDING GEAR,NOSE GEAR - BUCKLED
5. DIRECTIONAL CONTROL - UNCONTROLLED - PILOT IN COMMAND

Factual Information

Pilot Information

Certificate:	Foreign; Private	**Age:**	20, Male
Airplane Rating(s):	Single-engine Land	**Seat Occupied:**	Left
Other Aircraft Rating(s):	None	**Restraint Used:**	Seatbelt
Instrument Rating(s):	None	**Second Pilot Present:**	No
Instructor Rating(s):	None	**Toxicology Performed:**	No
Medical Certification:	Class 1 With Waivers/Limitations	**Last FAA Medical Exam:**	08/01/2007
Occupational Pilot:		**Last Flight Review or Equivalent:**	08/01/2007
Flight Time:	47 hours (Total, all aircraft), 47 hours (Total, this make and model), 6 hours (Pilot In Command, all aircraft), 47 hours (Last 90 days, all aircraft), 23 hours (Last 30 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	**Registration:**	N64197
Model/Series:	172P	**Aircraft Category:**	Airplane
Year of Manufacture:		**Amateur Built:**	No
Airworthiness Certificate:	Normal; Utility	**Serial Number:**	17275533
Landing Gear Type:	Tricycle	**Seats:**	4
Date/Type of Last Inspection:	11/01/2007, 100 Hour	**Certified Max Gross Wt.:**	2407 lbs
Time Since Last Inspection:		**Engines:**	1 Reciprocating
Airframe Total Time:	16708 Hours at time of accident	**Engine Manufacturer:**	Lycoming
ELT:	Installed, not activated	**Engine Model/Series:**	O-320-D2J
Registered Owner:	Ameriflyers of Texas Inc.	**Rated Power:**	160 hp
Operator:	Ameriflyers of Texas Inc.	**Operating Certificate(s) Held:**	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	**Condition of Light:**	Day
Observation Facility, Elevation:	XBP	**Distance from Accident Site:**	
Observation Time:	1508	**Direction from Accident Site:**	
Lowest Cloud Condition:	Clear	**Visibility**	10 Miles
Lowest Ceiling:	None	**Visibility (RVR):**	
Wind Speed/Gusts:	9 knots /	**Turbulence Type Forecast/Actual:**	/
Wind Direction:	230°	**Turbulence Severity Forecast/Actual:**	/
Altimeter Setting:	30.04 inches Hg	**Temperature/Dew Point:**	21°C / 4°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	FORT WORTH, TX (FTW)	**Type of Flight Plan Filed:**	Company VFR
Destination:		**Type of Clearance:**	VFR
Departure Time:		**Type of Airspace:**	

Airport Information

Airport:	BRIDGEPORT MUNI (1F9)	**Runway Surface Type:**	Asphalt
Airport Elevation:	852 ft	**Runway Surface Condition:**	Dry; Water--choppy
Runway Used:	17	**IFR Approach:**	None
Runway Length/Width:	4004 ft / 60 ft	**VFR Approach/Landing:**	Full Stop; Traffic Pattern

Wreckage and Impact Information

Crew Injuries:	1 None	**Aircraft Damage:**	Substantial
Passenger Injuries:	N/A	**Aircraft Fire:**	None
Ground Injuries:	N/A	**Aircraft Explosion:**	None
Total Injuries:	1 None	**Latitude, Longitude:**	33.175278, -97.828333

Administrative Information

Investigator In Charge (IIC):	Jason T Aguilera	**Report Date:**	12/20/2007
Additional Participating Persons:	Timothy D Wells; Fort Worth, Texas; Fort Worth, TX		
Publish Date:			
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.		
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov, or at 800-877-6799. Dockets released after this date are available at http://dms.ntsb.gov/pubdms/.		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.