National Transportation Safety Board
Aviation Accident Final Report

Location:	El Cajon, CA	**Accident Number:**	SEA08CA047
Date & Time:	12/14/2007, 1421 PST	**Registration:**	N567SP
Aircraft:	Cessna 172S	**Aircraft Damage:**	Substantial
Defining Event:		**Injuries:**	1 None
Flight Conducted Under:	Part 91: General Aviation - Instructional		

Analysis

The student pilot stated that she was practicing touch-and-go takeoffs and landings during her second solo flight. She completed three uneventfully. On the fourth one, her approach speed was higher than normal. She landed the airplane and rolled out on the runway. When she attempted to turn onto a taxiway, the airplane was going too fast, and she taxied off of the runway and into a ditch. The outboard 2 feet of the left wing was curved upward, and the right horizontal stabilizer and elevator were bent.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The excessive speed while turning off of the runway which resulted in a loss of aircraft control. The ditch was a factor.

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER
Phase of Operation: TAXI - FROM LANDING

Findings
1. (C) AIRSPEED - EXCESSIVE - PILOT IN COMMAND
2. (C) AIRCRAFT CONTROL - NOT MAINTAINED - PILOT IN COMMAND

Occurrence #2: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER
Phase of Operation: TAXI - FROM LANDING

Findings
3. (F) TERRAIN CONDITION - DITCH

Factual Information

Student Pilot Information

Certificate:	Student	**Age:**	19, Female
Airplane Rating(s):	None	**Seat Occupied:**	
Other Aircraft Rating(s):	None	**Restraint Used:**	Seatbelt, Shoulder harness
Instrument Rating(s):	None	**Second Pilot Present:**	
Instructor Rating(s):		**Toxicology Performed:**	
Medical Certification:	Class 1	**Last FAA Medical Exam:**	07/01/2007
Occupational Pilot:		**Last Flight Review or Equivalent:**	
Flight Time:	56 hours (Total, all aircraft), 56 hours (Total, this make and model), 41 hours (Last 90 days, all aircraft), 17 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	**Registration:**	N567SP
Model/Series:	172S	**Aircraft Category:**	Airplane
Year of Manufacture:		**Amateur Built:**	No
Airworthiness Certificate:	Normal; Utility	**Serial Number:**	172S8491
Landing Gear Type:	Tricycle	**Seats:**	
Date/Type of Last Inspection:		**Certified Max Gross Wt.:**	
Time Since Last Inspection:		**Engines:**	1 Reciprocating
Airframe Total Time:		**Engine Manufacturer:**	Lycoming
ELT:		**Engine Model/Series:**	IO-360-B1E
Registered Owner:	Scandinavian Aviation Academy	**Rated Power:**	
Operator:	Scandinavian Aviation Academy	**Operating Certificate(s) Held:**	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	**Condition of Light:**	Day
Observation Facility, Elevation:	KSEE, 388 ft msl	**Distance from Accident Site:**	0 Nautical Miles
Observation Time:	1247 PST	**Direction from Accident Site:**	0°
Lowest Cloud Condition:	Clear	**Visibility**	15 Miles
Lowest Ceiling:	None	**Visibility (RVR):**	
Wind Speed/Gusts:	Calm /	**Turbulence Type Forecast/Actual:**	/
Wind Direction:		**Turbulence Severity Forecast/Actual:**	/
Altimeter Setting:	30.19 inches Hg	**Temperature/Dew Point:**	
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	El Cajon, CA (SEE)	**Type of Flight Plan Filed:**	None
Destination:	El Cajon, CA (SEE)	**Type of Clearance:**	VFR
Departure Time:		**Type of Airspace:**	

Airport Information

Airport:	Gillespie Field (SEE)	**Runway Surface Type:**	Asphalt
Airport Elevation:	388 ft	**Runway Surface Condition:**	Dry
Runway Used:	27R	**IFR Approach:**	None
Runway Length/Width:	5342 ft / 100 ft	**VFR Approach/Landing:**	Full Stop

Wreckage and Impact Information

Crew Injuries:	1 None	**Aircraft Damage:**	Substantial
Passenger Injuries:	N/A	**Aircraft Fire:**	None
Ground Injuries:	N/A	**Aircraft Explosion:**	
Total Injuries:	1 None	**Latitude, Longitude:**	32.832500, -116.975833

Administrative Information

Investigator In Charge (IIC):	Kristi Dunks	**Report Date:**	01/31/2008
Additional Participating Persons:	Carl Allen; Federal Aviation Administration; San Diego, CA		
Publish Date:			
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.		
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov, or at 800-877-6799. Dockets released after this date are available at http://dms.ntsb.gov/pubdms/.		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.