National Transportation Safety Board
Aviation Accident Final Report

Location:	Spokane, WA	**Accident Number:**	SEA08CA044
Date & Time:	12/08/2007, 1030 PST	**Registration:**	N9048T
Aircraft:	Cessna 182	**Aircraft Damage:**	Substantial
Defining Event:		**Injuries:**	1 None
Flight Conducted Under:	Part 91: General Aviation - Positioning		

Analysis

The pilot reported that after an uneventful run-up, he taxied onto the runway and proceeded to takeoff. During takeoff initial climb, the engine lost power and he initiated a 180-degree turn towards the departure runway due to a lack of suitable terrain for a forced landing. During the forced landing, the airplane struck an airport perimeter fence and subsequently nosed into the ground. A post-accident inspection of the airframe and engine revealed no mechanical anomalies. The reason for the loss of engine power was undetermined.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The loss of engine power for undetermined reasons. Contributing factors were the lack of suitable terrain for the forced landing and the fence.

Findings

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL
Phase of Operation: TAKEOFF - INITIAL CLIMB

Findings
1. (C) REASON FOR OCCURRENCE UNDETERMINED

Occurrence #2: ON GROUND/WATER COLLISION WITH OBJECT
Phase of Operation: LANDING - ROLL

Findings
2. (F) OBJECT - FENCE
3. (F) TERRAIN CONDITION - NONE SUITABLE

Factual Information

Pilot Information

Certificate:	Commercial; Private	**Age:**	59, Male
Airplane Rating(s):	Multi-engine Land; Single-engine Land	**Seat Occupied:**	Left
Other Aircraft Rating(s):	Helicopter	**Restraint Used:**	Seatbelt, Shoulder harness
Instrument Rating(s):	Airplane	**Second Pilot Present:**	No
Instructor Rating(s):	None	**Toxicology Performed:**	
Medical Certification:	Class 2	**Last FAA Medical Exam:**	06/01/2007
Occupational Pilot:		**Last Flight Review or Equivalent:**	
Flight Time:	2250 hours (Total, all aircraft), 500 hours (Total, this make and model), 2150 hours (Pilot In Command, all aircraft), 11 hours (Last 90 days, all aircraft), 5 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	**Registration:**	N9048T
Model/Series:	182	**Aircraft Category:**	Airplane
Year of Manufacture:		**Amateur Built:**	No
Airworthiness Certificate:	Normal	**Serial Number:**	52948
Landing Gear Type:	Tricycle	**Seats:**	1
Date/Type of Last Inspection:		**Certified Max Gross Wt.:**	
Time Since Last Inspection:		**Engines:**	1 Reciprocating
Airframe Total Time:		**Engine Manufacturer:**	Continental
ELT:		**Engine Model/Series:**	O-470-R
Registered Owner:	FUN-AIRE INC	**Rated Power:**	
Operator:	Rex Minke	**Operating Certificate(s) Held:**	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	**Condition of Light:**	Day
Observation Facility, Elevation:		**Distance from Accident Site:**	
Observation Time:		**Direction from Accident Site:**	
Lowest Cloud Condition:	Clear	**Visibility**	
Lowest Ceiling:	None	**Visibility (RVR):**	
Wind Speed/Gusts:	Calm /	**Turbulence Type Forecast/Actual:**	/
Wind Direction:	Variable	**Turbulence Severity Forecast/Actual:**	/
Altimeter Setting:		**Temperature/Dew Point:**	-4°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Spokane, WA (KGEG)	**Type of Flight Plan Filed:**	None
Destination:	Ritzville, WA (NONE)	**Type of Clearance:**	None
Departure Time:	PST	**Type of Airspace:**	

Airport Information

Airport:	Spokane Felts Field (SFF)	**Runway Surface Type:**	Asphalt
Airport Elevation:		**Runway Surface Condition:**	Dry
Runway Used:	3R	**IFR Approach:**	None
Runway Length/Width:		**VFR Approach/Landing:**	Forced Landing

Wreckage and Impact Information

Crew Injuries:	1 None	**Aircraft Damage:**	Substantial
Passenger Injuries:	N/A	**Aircraft Fire:**	None
Ground Injuries:	N/A	**Aircraft Explosion:**	None
Total Injuries:	1 None	**Latitude, Longitude:**	47.619722, -117.533611

Administrative Information

Investigator In Charge (IIC):	Joshua D Cawthra	**Report Date:**	01/31/2008
Additional Participating Persons:	James Black; Spokane, Washington		
Publish Date:			
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.		
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov, or at 800-877-6799. Dockets released after this date are available at http://dms.ntsb.gov/pubdms/.		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.