National Transportation Safety Board
Aviation Accident Final Report

Location:	Wausau, WI	**Accident Number:**	CHI08CA047
Date & Time:	12/08/2007, 1630 CST	**Registration:**	N2151J
Aircraft:	Cessna Skyhawk 172	**Aircraft Damage:**	Substantial
Defining Event:		**Injuries:**	1 None
Flight Conducted Under:	Part 91: General Aviation - Personal		

Analysis

The pilot reported completing three takeoffs and full stop landings on runway 30, and then he switched to runway 04 (3078 feet long, 100 feet wide, ice, snow covered). After landing on runway 04, the airplane skidded on a patch of packed snow and the pilot reported that he "Lost control. Plane ran off side of runway." The pilot tried to hold the yoke back but the nosewheel dug into soft snow on the side of the runway and the airplane nosed over. The pilot was not injured. He did not report any mechanical malfunctions. The right wing rear spar was bent.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot failed to maintain directional control during the landing roll. Factors that contributed to the accident included the snow on the runway and the snowbank.

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER
Phase of Operation: LANDING - ROLL

Findings
1. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND
2. (F) TERRAIN CONDITION - SNOW COVERED
3. (F) TERRAIN CONDITION - RUNWAY

Occurrence #2: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER
Phase of Operation: LANDING - ROLL

Findings
4. (F) TERRAIN CONDITION - SNOWBANK

Occurrence #3: NOSE OVER
Phase of Operation: LANDING

Factual Information

Pilot Information

Certificate:	Private	**Age:**	61, Male
Airplane Rating(s):	Single-engine Land	**Seat Occupied:**	
Other Aircraft Rating(s):	None	**Restraint Used:**	Seatbelt, Shoulder harness
Instrument Rating(s):	None	**Second Pilot Present:**	No
Instructor Rating(s):	None	**Toxicology Performed:**	No
Medical Certification:	Class 3 With Waivers/Limitations	**Last FAA Medical Exam:**	04/01/2006
Occupational Pilot:		**Last Flight Review or Equivalent:**	
Flight Time:	158 hours (Total, all aircraft), 158 hours (Total, this make and model), 57 hours (Pilot In Command, all aircraft), 6 hours (Last 90 days, all aircraft), 2 hours (Last 30 days, all aircraft), 0 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	**Registration:**	N2151J
Model/Series:	Skyhawk 172	**Aircraft Category:**	Airplane
Year of Manufacture:		**Amateur Built:**	No
Airworthiness Certificate:	Normal	**Serial Number:**	17-80679
Landing Gear Type:	Tricycle	**Seats:**	
Date/Type of Last Inspection:	08/01/2007, Annual	**Certified Max Gross Wt.:**	2450 lbs
Time Since Last Inspection:	75 Hours	**Engines:**	1 Reciprocating
Airframe Total Time:	5950 Hours at time of accident	**Engine Manufacturer:**	Textron Lycoming
ELT:	Installed, not activated	**Engine Model/Series:**	IO-360
Registered Owner:	Wausau Flying Service	**Rated Power:**	160 hp
Operator:	Wausau Flying Service	**Operating Certificate(s) Held:**	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	**Condition of Light:**	Day
Observation Facility, Elevation:	AUW	**Distance from Accident Site:**	
Observation Time:	1654	**Direction from Accident Site:**	
Lowest Cloud Condition:	Clear	**Visibility**	10 Miles
Lowest Ceiling:	Overcast / 11000 ft agl	**Visibility (RVR):**	
Wind Speed/Gusts:	6 knots /	**Turbulence Type Forecast/Actual:**	/
Wind Direction:	290°	**Turbulence Severity Forecast/Actual:**	/
Altimeter Setting:	30.4 inches Hg	**Temperature/Dew Point:**	-13°C / -18°C
Precipitation and Obscuration:			
Departure Point:	Wausau, WI (AUW)	**Type of Flight Plan Filed:**	None
Destination:	(AUW)	**Type of Clearance:**	None
Departure Time:	CST	**Type of Airspace:**	

Airport Information

Airport:	Wausau Downtown (AUW)	**Runway Surface Type:**	Asphalt
Airport Elevation:	1201 ft	**Runway Surface Condition:**	Ice; Snow; Wet
Runway Used:	04	**IFR Approach:**	None
Runway Length/Width:	3078 ft / 100 ft	**VFR Approach/Landing:**	Traffic Pattern

Wreckage and Impact Information

Crew Injuries:	1 None	**Aircraft Damage:**	Substantial
Passenger Injuries:	N/A	**Aircraft Fire:**	None
Ground Injuries:	N/A	**Aircraft Explosion:**	None
Total Injuries:	1 None	**Latitude, Longitude:**	44.926111, -89.626389

Administrative Information

Investigator In Charge (IIC):	Jim Silliman	**Report Date:**	01/31/2008
Additional Participating Persons:	Jan Gerstner; FAA-MKE-FSDO		
Publish Date:			
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.		
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov, or at 800-877-6799. Dockets released after this date are available at http://dms.ntsb.gov/pubdms/.		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.