National Transportation Safety Board
Aviation Accident Final Report

Location:	Madill, OK	**Accident Number:**	DFW08CA044
Date & Time:	11/30/2007, 1200 CST	**Registration:**	N6135M
Aircraft:	Cessna 152	**Aircraft Damage:**	Substantial
Defining Event:		**Injuries:**	1 None
Flight Conducted Under:	Part 91: General Aviation - Instructional		

Analysis

The 28-hour solo student pilot landed with a crosswind condition and lost control of the airplane during the landing roll. The mishap occurred during the student's seventh solo landing of the day. The pilot stated that after the airplane landed "the wind switched from a crosswind to a tail wind and back" to crosswind. The airplane departed the runway, the nose gear collapsed in the soft terrain, and the propeller contacted the ground. Examination of the airplane by an inspector from the Federal Aviation Administration revealed structural damage to the engine firewall. The winds at the time of the accident were reported as a 90 degree crosswind to the active runway at 8 knots.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot failed to maintain directional control during landing roll. A contributing factor was the crosswind.

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER
Phase of Operation: LANDING - ROLL

Findings
1. (F) WEATHER CONDITION - CROSSWIND
2. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

Factual Information

Student Pilot Information

Certificate:	Student	**Age:**	32, Male
Airplane Rating(s):	None	**Seat Occupied:**	Left
Other Aircraft Rating(s):	None	**Restraint Used:**	Seatbelt, Shoulder harness
Instrument Rating(s):	None	**Second Pilot Present:**	No
Instructor Rating(s):	None	**Toxicology Performed:**	No
Medical Certification:	Class 3 Without Waivers/Limitations	**Last FAA Medical Exam:**	09/01/2007
Occupational Pilot:		**Last Flight Review or Equivalent:**	
Flight Time:	28 hours (Total, all aircraft), 24 hours (Total, this make and model), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	**Registration:**	N6135M
Model/Series:	152	**Aircraft Category:**	Airplane
Year of Manufacture:		**Amateur Built:**	No
Airworthiness Certificate:	Normal	**Serial Number:**	15284628
Landing Gear Type:	Tricycle	**Seats:**	
Date/Type of Last Inspection:		**Certified Max Gross Wt.:**	
Time Since Last Inspection:		**Engines:**	1 Reciprocating
Airframe Total Time:		**Engine Manufacturer:**	Lycoming
ELT:	Installed, not activated	**Engine Model/Series:**	O-235
Registered Owner:	Versatile Aviation Inc	**Rated Power:**	115 hp
Operator:	Versatile Aviation Inc	**Operating Certificate(s) Held:**	None
Operator Does Business As:	Versatile Aviation Inc	**Operator Designator Code:**	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	**Condition of Light:**	Day
Observation Facility, Elevation:	KADM	**Distance from Accident Site:**	
Observation Time:	1355	**Direction from Accident Site:**	
Lowest Cloud Condition:	Scattered / 12000 ft agl	**Visibility**	10 Miles
Lowest Ceiling:	None	**Visibility (RVR):**	
Wind Speed/Gusts:	8 knots /	**Turbulence Type Forecast/Actual:**	/
Wind Direction:	90°	**Turbulence Severity Forecast/Actual:**	/
Altimeter Setting:	30.19 inches Hg	**Temperature/Dew Point:**	13°C / 7°C
Precipitation and Obscuration:			
Departure Point:	Ardmore, OK (1F0)	**Type of Flight Plan Filed:**	None
Destination:	Madill, OK (1F4)	**Type of Clearance:**	None
Departure Time:	1100 CST	**Type of Airspace:**	

Airport Information

Airport:		**Runway Surface Type:**	
Airport Elevation:		**Runway Surface Condition:**	
Runway Used:		**IFR Approach:**	
Runway Length/Width:		**VFR Approach/Landing:**	

Wreckage and Impact Information

Crew Injuries:	1 None	**Aircraft Damage:**	Substantial
Passenger Injuries:	N/A	**Aircraft Fire:**	None
Ground Injuries:	N/A	**Aircraft Explosion:**	None
Total Injuries:	1 None	**Latitude, Longitude:**	34.144444, -96.811389

Administrative Information

Investigator In Charge (IIC):	William H Gamble	**Report Date:**	01/31/2008
Additional Participating Persons:	Robert L Newell; Oklahoma City		
Publish Date:			
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.		
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov, or at 800-877-6799. Dockets released after this date are available at http://dms.ntsb.gov/pubdms/.		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.