National Transportation Safety Board
Aviation Accident Final Report

Location:	Holbrook, AZ	**Accident Number:**	LAX08CA041
Date & Time:	12/22/2007, 1230 MST	**Registration:**	N418MS
Aircraft:	Found Acft FBA-2C2	**Aircraft Damage:**	Substantial
Defining Event:		**Injuries:**	2 Minor, 2 None
Flight Conducted Under:	Part 91: General Aviation - Personal		

Analysis

The pilot landed on the runway in a 3-point touchdown and reduced all engine power and pulled the stick back to keep the tail down. Despite applying right rudder to keep the airplane centered on the runway and not moving to the left, the pilot was unable to maintain directional control. The pilot reported that she added full engine power too late and the airplane ground looped striking its propeller. The pilot said there were no preimpact mechanical malfunctions or failures.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's failure to maintain directional control during landing rollout, which resulted in an inadvertent ground loop.

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER
Phase of Operation: LANDING - ROLL

Findings
1. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND
2. (C) GROUND LOOP/SWERVE - INADVERTENT - PILOT IN COMMAND

Occurrence #2: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER
Phase of Operation: LANDING - ROLL

Findings
3. TERRAIN CONDITION - RUNWAY

Factual Information

Pilot Information

Certificate:	Private	**Age:**	37, Female
Airplane Rating(s):	Single-engine Land	**Seat Occupied:**	
Other Aircraft Rating(s):	None	**Restraint Used:**	Seatbelt, Shoulder harness
Instrument Rating(s):	None	**Second Pilot Present:**	
Instructor Rating(s):		**Toxicology Performed:**	
Medical Certification:	Class 3	**Last FAA Medical Exam:**	10/01/2005
Occupational Pilot:		**Last Flight Review or Equivalent:**	
Flight Time:	240 hours (Total, all aircraft), 74 hours (Total, this make and model), 27 hours (Last 90 days, all aircraft), 17 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Found Acft	**Registration:**	N418MS
Model/Series:	FBA-2C2	**Aircraft Category:**	Airplane
Year of Manufacture:		**Amateur Built:**	No
Airworthiness Certificate:	Normal	**Serial Number:**	101
Landing Gear Type:	Tailwheel	**Seats:**	
Date/Type of Last Inspection:		**Certified Max Gross Wt.:**	
Time Since Last Inspection:		**Engines:**	1 Reciprocating
Airframe Total Time:		**Engine Manufacturer:**	Lycoming
ELT:		**Engine Model/Series:**	IO-540-LIC5
Registered Owner:	Carwil, LLC.	**Rated Power:**	
Operator:	Kristin A. Carriere	**Operating Certificate(s) Held:**	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	**Condition of Light:**	Day
Observation Facility, Elevation:		**Distance from Accident Site:**	
Observation Time:		**Direction from Accident Site:**	
Lowest Cloud Condition:	Clear	**Visibility**	10 Miles
Lowest Ceiling:	None	**Visibility (RVR):**	
Wind Speed/Gusts:	Light and Variable /	**Turbulence Type Forecast/Actual:**	/
Wind Direction:		**Turbulence Severity Forecast/Actual:**	/
Altimeter Setting:		**Temperature/Dew Point:**	10°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Winnemucca, NV (WMC)	**Type of Flight Plan Filed:**	None
Destination:	Holbrook, AZ (P14)	**Type of Clearance:**	None
Departure Time:		**Type of Airspace:**	

Airport Information

Airport:	Holbrook (P14)	**Runway Surface Type:**	Asphalt
Airport Elevation:	5262 ft	**Runway Surface Condition:**	Dry
Runway Used:	21	**IFR Approach:**	None
Runway Length/Width:	6698 ft / 75 ft	**VFR Approach/Landing:**	Full Stop

Wreckage and Impact Information

Crew Injuries:	1 Minor	**Aircraft Damage:**	Substantial
Passenger Injuries:	1 Minor, 2 None	**Aircraft Fire:**	None
Ground Injuries:	N/A	**Aircraft Explosion:**	
Total Injuries:	2 Minor, 2 None	**Latitude, Longitude:**	35.933889, -110.133611

Administrative Information

Investigator In Charge (IIC):	Wayne Pollack	**Report Date:**	02/28/2008
Additional Participating Persons:	Bill Sapp; Federal Aviation Administration; Scottsdale, AZ		
Publish Date:			
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.		
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov, or at 800-877-6799. Dockets released after this date are available at http://dms.ntsb.gov/pubdms/.		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.