National Transportation Safety Board
Aviation Accident Factual Report

Location:	Guario, Venezuela	**Accident Number:**	MIA08WA060
Date & Time:	12/09/2007, 1730 AST	**Registration:**	
Aircraft:	Cessna T210	**Aircraft Damage:**	Destroyed
Defining Event:		**Injuries:**	2 Fatal
Flight Conducted Under:	Non-U.S., Non-Commercial		

On December 9, 2007, about 1730 Atlantic standard time, a Cessna T210, of Venezuelan registration, YV-1221, collided with electrical power lines near Guarico, Venezuela. Visual meteorological conditions prevailed and flight plan information is unknown. The pilot and passenger received fatal injuries. The aircraft was destroyed. The flight originated from the San Juan de Los Morros Airport, Guarico, Venezuela, earlier that day, at an unknown time.

Information from the Venezuelan government states that the airplane collided with high tensioned electrical power lines. The airplane then impacted the ground and a post impact fire ensued, consuming the airplane.

The investigation is under the jurisdiction of the Government of Venezuela. Further information pertaining to this accident may be obtained from:

Junta Investigadora de Accidentes de Aviación

Ministerio de Infraestructura

Republica Bolivariana de Venezuela

Av. Francisco de Miranda

Torre MINFRA, piso-20

Caracas, Republica de Bolivariana de Venezuela

This report is for informational purposes only and contains only information released by or obtained for the Government of Venezuela.

Pilot Information

Certificate:	**Age:**
Airplane Rating(s):	**Seat Occupied:**
Other Aircraft Rating(s):	**Restraint Used:**
Instrument Rating(s):	**Second Pilot Present:**
Instructor Rating(s):	**Toxicology Performed:**
Medical Certification:	**Last FAA Medical Exam:**
Occupational Pilot:	**Last Flight Review or Equivalent:**
Flight Time:	

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	**Registration:**	
Model/Series:	T210	**Aircraft Category:**	Airplane
Year of Manufacture:		**Amateur Built:**	No
Airworthiness Certificate:		**Serial Number:**	
Landing Gear Type:		**Seats:**	
Date/Type of Last Inspection:		**Certified Max Gross Wt.:**	
Time Since Last Inspection:		**Engines:**	
Airframe Total Time:		**Engine Manufacturer:**	
ELT:		**Engine Model/Series:**	
Registered Owner:		**Rated Power:**	
Operator:		**Operating Certificate(s) Held:**	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	**Condition of Light:**	
Observation Facility, Elevation:	SVBS	**Distance from Accident Site:**	
Observation Time:	1700	**Direction from Accident Site:**	
Lowest Cloud Condition:	Few / 1300 ft agl	**Visibility**	10 Miles
Lowest Ceiling:	None	**Visibility (RVR):**	
Wind Speed/Gusts:	6 knots /	**Turbulence Type Forecast/Actual:**	/
Wind Direction:	200°	**Turbulence Severity Forecast/Actual:**	/
Altimeter Setting:	30.12 inches Hg	**Temperature/Dew Point:**	29°C / 19°C
Precipitation and Obscuration:			
Departure Point:	San Juan Morros (SVJM)	**Type of Flight Plan Filed:**	None
Destination:		**Type of Clearance:**	
Departure Time:	AST	**Type of Airspace:**	

Airport Information

Airport:		**Runway Surface Type:**	
Airport Elevation:		**Runway Surface Condition:**	
Runway Used:		**IFR Approach:**	
Runway Length/Width:		**VFR Approach/Landing:**	

Wreckage and Impact Information

Crew Injuries:	1 Fatal	**Aircraft Damage:**	Destroyed
Passenger Injuries:	1 Fatal	**Aircraft Fire:**	
Ground Injuries:	N/A	**Aircraft Explosion:**	
Total Injuries:	2 Fatal	**Latitude, Longitude:**	9.906667, -67.355000

Administrative Information

Investigator In Charge (IIC):	Jose L Obregon
Additional Participating Persons:	Javier Rodriguez; FAA Maimi International
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov, or at 800-877-6799. Dockets released after this date are available at http://dms.ntsb.gov/pubdms/.