

Laptop Not Powering On

Step 1 – Check the Power Adapter

I would check whether the charger is properly connected to the laptop and power socket. This helps confirm that the laptop is receiving power.

Step 2 – Check the Power Indicator

I would check for any charging light or power indicator. This helps identify whether the laptop is receiving electrical power.

Step 3 – Check the Battery

I would check whether the battery is properly connected and look for any visible damage. This helps identify a possible battery problem.

Step 4 – Try a Basic Power Reset

I would disconnect the charger and, if the battery is removable, remove it. Then I would reconnect the power and try starting the laptop again.

Step 5 – Check for Hardware Signs

I would listen for fan sounds or check whether any LEDs turn on when the power button is pressed. This helps determine whether the problem may be related to the power button, adapter, battery or internal hardware.

Conclusion:

These steps help narrow down whether the laptop's power problem is caused by the charger, battery, connection or another hardware component.

Troubleshooting a Blank Monitor Screen

Step 1 – Check the Monitor Power

I would check that the monitor is switched on and that its power cable is properly connected.

Step 2 – Check the Display Cable

I would check the HDMI, DisplayPort or other video cable at both ends to make sure it is securely connected.

Step 3 – Check the Correct Input Source

I would check the monitor's input/source setting and select the port that is actually being used.

Step 4 – Check the PC Display Connection

I would make sure the display cable is connected to the correct video output on the computer.

Step 5 – Check Basic Display Settings

If Windows is running, I would check the display settings and try using Windows + P to select an appropriate display mode.

Step 6 – Restart and Test

I would restart the computer and, if possible, test the monitor or cable with another known-working system.

Conclusion:

These checks help determine whether the blank screen is caused by the monitor power, cable, input selection, computer connection or display settings.

Troubleshooting an Unresponsive Wireless Mouse

Step 1 – Check the Mouse

I would check whether the mouse is switched on and whether its battery has enough charge.

Step 2 – Check the USB Receiver

I would make sure the wireless receiver is properly connected to the computer's USB port.

Step 3 – Test Another USB Port

I would connect the receiver to another USB port. If the mouse works there, the original USB port may have a problem.

Step 4 – Test the Mouse on Another Computer

I would connect the mouse and receiver to another computer. If it still does not work, the mouse or receiver may be faulty.

Step 5 – Check System Settings

I would check Windows settings and Device Manager to see whether the mouse is detected correctly and whether there is any warning or error.

Step 6 – Reconnect the Mouse

If necessary, I would re-pair the mouse with its receiver according to the manufacturer's instructions.

Conclusion:

Testing the mouse, receiver, USB ports and system settings separately helps identify

whether the problem is with the mouse itself, the USB connection or the computer.

Troubleshooting an Overheating Gaming PC

Possible Cause 1 – Dusty or Blocked Fans

I would check the CPU and case fans for dust and make sure they are spinning properly. Dust buildup can reduce airflow and increase the temperature.

Possible Cause 2 – Faulty or Slow Fan

I would check whether the CPU and case fans are working correctly. A fan that is not spinning properly can cause the system to overheat.

Possible Cause 3 – Old or Improper Thermal Paste

I would check the thermal paste between the CPU and its cooler. If the paste is old or not

applied correctly, heat may not transfer efficiently to the cooler.

How I Would Check:

I would first inspect the fans and airflow, then check for dust buildup. If the cooling system still does not work properly, I would have the thermal paste checked or replaced by a technician/instructor.

Conclusion:

The three common hardware causes are poor airflow from dust, faulty cooling fans, and ineffective thermal paste. Checking these areas can help identify the cause of overheating and unexpected shutdowns.