

Date: 21 August 2017 Contact: Ms. Juliet Hudson

(202) 372-1173

Port Security Advisory (2-17)

A. Background:

The Maritime Transportation Security Act of 2002 (MTSA) has mandated that the United States Coast Guard evaluate the effectiveness of anti-terrorism measures in foreign ports and provides for the imposition of conditions of entry on vessels arriving to the United States from countries that do not maintain effective anti-terrorism measures (MTSA, 46 U.S.C. §§ 70108 - 70110).

The Coast Guard has determined that Micronesia is not maintaining effective anti-terrorism measures in all of its ports. Actions required as listed in paragraphs C and D of this Port Security Advisory take effect for vessels that arrive in the United States upon on or after September 5, 2017, after visiting ports in the Federated States of Micronesia as one of their last five ports of call.

B. Countries Affected:

The Coast Guard has determined that ports in the following countries are not maintaining effective antiterrorism measures:

Cambodia

Cameroon

Exceptions	IMO Port Number
Ebome Marine Terminal	CM394-0001
Quai GETMA (LAMNALCO Base) Facility	CMDLA-0005
Société Nationale de Raffinage (SONARA) Terminal	CMLIT-0001
(also known as Cap Limboh Terminal)	
Kome-Kribi 1	CM234-0001
Douala International Terminal (also known as Douala	CMDLA-0002
Containers)	
Moudi Terminal	CMMOU-0001

Comoros

Cote d' Ivoire



Equatorial Guinea

Exceptions	IMO Port Number
Ceiba	GQ362-0001/0002
K-5 Oil Center	IMO number not listed
Luba	GQLUB-0001
Punta Europa Terminal	GQ368-0001
Zafiro Marine Terminal	GQ370-0001

The Gambia

Guinea-Bissau

Iran

Liberia

Exceptions	IMO Port Number
Firestone Facility	IMO number not listed;
Port of Monrovia	LRMLW-0001

Libya

Note: Vessels are also advised to proceed with extreme caution when approaching all Libyan oil terminals, particularly in eastern Libya, due to potential violent and criminal activity based upon recent attempts by armed, non-state actors to engage in illicit export of oil. UN Security Council Resolution 2146 authorizes the UN Sanctions Committee to impose certain measures on vessels attempting to illicitly export crude oil from Libya. This resolution imposes several restrictions regarding loading, transporting, or discharging crude oil from Libya which may include the possible denial of port entry. Further information regarding the UN Security Council Resolution can be found at:

http://www.un.org/News/Press/docs//2014/sc11325.doc.htm

Madagascar

Exceptions	IMO Port Number
Toamasina (also known as Tamatave)	MGTMM-0001

Micronesia

Nauru

-More-



Nigeria

Exceptions	IMO Port Number (under revision)
APP Apapa Bulk Terminal	
APP AP Moller Terminal	
APP Greenview Terminal	
BON Bonny River Terminal	
BON NLGN Bonny Terminal	
BON SPDC Bonny Offshore Terminal	
CBQ FSO YOHO (Exxon Mobile)	
CBQ Logistics Base	
CBQ McIver Wharf	
CBQ Port Terminal A	
CBQ QIT BOP	
ESC Escra BOP	
ESC LPG-FSO	
FOR Forcados Offshore Terminal	
ONN FLT	
ONN FOT	
TIN Dantata MRS Terminal	
TIN FSL	
TIN P&CH Terminal C	
TIN Snake Island Integrated Free Zone	
TIN PTML Terminal E	
TIN TICT Terminal B	

α			D •	•
San	Tome	and	Prin	cine
Duo	I OIIIC	ullu		CIPC

Syria

Timor-Leste

Venezuela

-More-

Yemen

Exceptions	IMO Port Number
Balhaf LNG Terminal	IMO number not listed
NOTE: The U.S. Coast Guard has separate, more	
stringent security protocols in place for vessels	
arriving to the United States from Balhaf. Vessels	
planning to arrive to the United States from Balhaf	
should contact the cognizant U.S. Coast Guard	
Captain of the Port well in advance.	

C. Actions Required by Vessels Visiting Countries Affected:

All vessels arriving to the United States that visited the countries listed in paragraph B (with exceptions noted) during their last five port calls must take actions 1 through 5 listed below while in the countries listed in paragraph B as a condition of entry into U.S. ports:

- 1. Implement measures per the ship's security plan equivalent to Security Level 2;
- 2. Ensure that each access point to the ship is guarded and that the guards have total visibility of the exterior (both landside and waterside) of the vessel. Guards may be:
 - provided by the ship's crew, however, additional crewmembers should be placed on the ship if necessary to ensure that limits on maximum hours of work are not exceeded and/or minimum hours of rest are met, or
 - provided by outside security forces approved by the ship's master and Company Security Officer.
- 3. Attempt to execute a Declaration of Security;
- 4. Log all security actions in the ship's security records; and
- 5. Report actions taken to the cognizant U.S. Coast Guard Captain of the Port prior to arrival in the U.S.

Vessels that visited the countries listed in paragraph B (with exceptions noted) on or after the effective date in paragraph A, during their last five port calls will be boarded or examined by the Coast Guard to ensure the vessel took the required actions. Failure to properly implement the actions listed in paragraph C.1 through C.5 may result in delay or denial of entry into the United States.

-More-



D. Actions Required by Vessels in U.S. Ports:

Based on the findings of the Coast Guard boarding or examination, the vessels that visited the countries listed in paragraph B (with exceptions noted) on or after the effective date in paragraph A <u>may</u> be required to ensure that each access point to the ship is guarded by armed security guards and that they have total visibility of the exterior (both landside and waterside) of the vessel while in U.S. ports. The number and location of the guards must be acceptable to the cognizant U.S. Coast Guard Captain of the Port. For those vessels that have demonstrated good security compliance and can document that they took the measures called for in C.1. through C.4. above, the armed security guard requirement will normally be waived.

###