




WorkSafety

SMART SAFETY





Welcome Back

Secure access for authorized
personnel

Email or Username

 user@worksafety.gov

Password

[Forgot password?](#)





☐ Keep me signed in

Sign In

+

New Analysis

Start an AI risk analysis in seconds.

Start Now >

Pending Analysis

3 PENDING

- North Sector

10/01

● Not synced

Assembly

09/01

● Not synced

External

08/01

● Not synced



New Inspection

STEP 1: ENVIRONMENT

Mandatory



Construction

Tap to select



Industry

Tap to select



Other

Tap to select



STEP 2: CATEGORY

Standard

General Safety




Continue >



 **PRIVACY MODE ON**

Identified faces will be automatically blurred (GDPR).



AI: Object Detection (Perseu) Enabled




 **PRIVACY MODE ON**

Identified faces will be automatically blurred (GDPR).



Tap to Review



AI: Object Detection (Perseu) Enabled





Syncing...



Visual Analysis (Perseu AI)
Detecting PPE & Risks...



Regulatory Check (Sofia NLP)
Mapping Bau-Wegweiser...



Syncing...



Visual Analysis (Perseu AI)

Detecting PPE & Risks...



Regulatory Check (Sofia NLP)

Mapping Bau-Wegweiser...



Risks Detected

Case #12345 • Validation



TOTAL RISKS

05



COMPLIANCE

82%



Action Checklist

JAN 10, 2026

RISK TYPE	LOCATION	SEVERITY	ACTION
☐ Missing Guardrail	Platform L2	CRITICAL	Immediate Install
☐ PPE Violation	Zone A	HIGH	Warning Issued
☐ Blocked Exit	Corridor B	MEDIUM	Clear Area
☐ Exposed Wiring	Panel 4	HIGH	Electrician Called
☐ Slippery Floor	Entrance	LOW	Signage Added

Reject

Confirm



Review

Case

#12345



ANALYSIS RESULT



View Risks



All Cases

Pending 2

📄

#INSP-2026-001

📅 10/01

• Construction

⚠️ PENDING

DETAILS ↗

📄

#INSP-2026-002

📅 09/01

• Construction

✅ APPROVED

DETAILS ↗

🏭

#INSP-2026-003

📅 08/01

• Industry

✅ APPROVED

DETAILS ↗

📦

#INSP-2026-004

📅 07/01

• Other


⚠️ PENDING

DETAILS ↗



#INSP-2026-001

DRAFT (AI)



DATE

Jan 10, 2026

LOCATION

North Sector

AI Analysis

PERSEU AI v2.0



Missing Guardrail (NR-35 / DIN 4420)

Conf: 94%

Accept

Reject



Worker without Helmet (PPE)

Conf: 88%

Accept

Reject

Suggested Norms

- DIN 4420-1:** Requirements for working and protective scaffolds.
- NR-35 (Brasil):** Work at height - Mandatory risk analysis before starting activities.

Finish Validation >



Inspection Report
CASE #12345



ENVIRONMENT
Construction



DATE
01/10/2026



EVIDENCE
Attached images



CONFIRMED RISKS
2 Incidents

✓ FINISH

Share Report

Download PDF

Safety Inspection Report

LOCATION

 North Sector - Construction

INSPECTOR

 Alex Inspector (ID: 8842)

EVIDENCE & FINDINGS



Fig 1. Site Capture - 10:42 AM

CRITICAL

94% Confidence

Missing Guardrail

Violation of NR-35 / DIN 4420. Fall hazard detected on Level 2 platform edge.

WARNING

88% Confidence

PPE Violation

Worker detected without safety helmet in active construction zone.

AI RECOMMENDATIONS

IMMEDIATE ACTION: Stop work in Sector North until guardrails are installed.

Issue formal warning to site supervisor regarding PPE compliance.

Schedule follow-up inspection for Jan 12, 2026.

AUTHORIZED SIGNATURE

Sarah Manager

Sarah Manager

Manager ID: 4421

WORKSAFETY
APPROVED

10/01/2026