

SYLLABUS :-

Mine Surveying Laboratory - Survey and a plot of a given area by traversing by (i) Chain and prismatic compass; and (ii) Total station. 0-0-3 - 289 - - Measurement of horizontal angle by Repetition and Re iteration method using Vernier Theodolite - Determination of bubble tube sensitivity and tacheometric constant of a Dumpy level. - Transfer of bench mark by Fly leveling using dumpy level and establish a road profile by rise and fall method. - Map upgradation by plane table method. - Transfer of reduced levels on surface to the underground working by Weisbach triangle method. - Introduction to GPS, Brunton, and dip fault problems