

Production Stakeholders & Questions (VDI 2206)




Stakeholder questions:

Resource function:
When is the **Rework Selection False Positive Rate** high?


Production quality:
Why is the **Welding issue rate** high?

Product, Process & Resource Assets (PPR, PAN, VDI 3682) with Logistics for a Flexible Production System


Products & Processes



Process Skills



Manufacturing Resources



Production Data Space (PDS, VDI 2206)

Production system variability model and configurations

Product AAS: Profile

Resource AAS: Welding Robot


Resource AAS: Automatic Optical Inspection System

Production Operation Data


Process Recipes (required accuracy)

FMEA Cause & Effect Network (CEN, DIN 60812)


Process Laser Welding




Process Laser Welding Skills




A Welding Seam Inspect. Sys. w/camera




B Welding Seam Inspect. Sys. w/LIDAR




Welding System Resource with camera







Input Products



Pre-Processing



Legend:



Dependency Links:

- ← Product-Process PPR-to-CEN Dep.
 - ↔ Process-Resource PDS-to-CEN Dep.
 - Cause-Effect CEN Dependencies
- (arrows are marker pairs):
- e1.1 E1.1 PPR-to-CEN Dep.
- c2.1 C2.1 PDS-to-CEN Dep.
- c1.1 C1.1 CEN Dependencies
- Upper case Letter marks arrow head; Lower case Letter marks arrow base.