

Production Stakeholders & Questions (VDI 2206)




Stakeholder questions:

Resource function:
When is the **Rework Selection False Positive Rate** high?


Production quality:
Why is the **Welding issue rate** high?

Product, Process & Resource Assets (PPR, PAN, VDI 3682) with Logistics for a Flexible Production System


Products & Processes



Process Skills



Manufacturing Resources



Production Data Space (PDS, VDI 2206)

Production system variability model and configurations

Product AAS: Profile [c7.1] [c6.2]

Resource AAS: Welding Robot [c5.2] [c3.1]


Resource AAS: Automatic Optical Inspection System [c3.2] [c3.1] [c2.1]

Production Operation Data


Process Recipes (required accuracy)

FMEA Cause & Effect Network (CEN, DIN 60812)


Process Laser Welding




Process Laser Welding Skills




A Welding Seam Inspect. Sys. w/camera




B Welding Seam Inspect. Sys. w/LIDAR




Welding System Resource with camera




Input Products



Pre-Processing



Legend:



Dependency Links:

- ← Product-Process
- ↔ Process-Resource
- Cause-Effect

(arrows are marker pairs):

[e1.1] [E1.1] PPR-to-CEN Dep.

[c2.1] [C2.1] PDS-to-CEN Dep.

[c1.1] [C1.1] CEN Dependencies

Upper case letter marks arrow head; Lower case letter marks arrow base.