



मंगलूर रिफाइनरी एण्ड पेट्रोकेमिकल्स लिमिटेड

MANGALORE REFINERY AND PETROCHEMICALS LIMITED

अनुसूची 'अ' के अंतर्गत भारत सरकार का उद्यम SCHEDULE 'A' GOVT. OF INDIA ENTERPRISE
(ऑयल एण्ड नेचुरल गैस कॉर्पोरेशन लिमिटेड की सहायक कंपनी A SUBSIDIARY OF OIL AND NATURAL GAS CORPORATION LIMITED)
आई.एस.ओ. 9001, 14001 एवं 50001 प्रमाणित कंपनी AN ISO 9001, 14001 AND 50001 CERTIFIED COMPANY
सीआईएन / CIN : L19200KA1988GOI008959 , Website : www.mrpl.co.in

30/09/2026

The Assistant General Manager, Listing Compliance, BSE Limited Scrip Code: 500109, ISIN: INE103A01014 Scrip Code (Debenture): 959162, 959250, 973692	The Compliance & Listing Department National Stock Exchange of India Limited Symbol: MRPL, Series: EQ, ISIN: INE103A01014 Debt Security: INE103A08019, INE103A08035, INE103A08050
---	--

Dear Sir,

Subject: MRPL Fire Incident 30.09.2026 – Further Update

With reference to subject matter, please find enclosed press release dated 30th September 2026 titled “MRPL Fire Incident – Further Update”.

This is for your information and record please.

Thanking You,

Yours faithfully,
For Mangalore Refinery and Petrochemicals Limited

Premachandra Rao G
Company Secretary

PREMACHANDRA RAO
GURPUR

Digitally signed by
PREMACHANDRA RAO GURPUR
Date: 2026.09.30 18:25:33 +05'30'

Encl: A/a



PRESS RELEASE

मंगलूर रिफाइनरी एण्ड पेट्रोकेमिकल्स लिमिटेड Mangalore Refinery & Petrochemicals Ltd. (MRPL)
A Govt. of India Enterprise and ONGC Subsidiary, Kuthethur P.O, Mangaluru - 575030.

MRPL Fire Incident: Further Updates.

Mangaluru, 30th September 2026

The fire incident that occurred at MRPL at around 12:20 hrs today was brought under control and completely extinguished by 14:47 hrs.

During the subsequent combing and inspection operations following the firefighting activity, the body of one deceased person was found at the affected site.

One person who sustained burn injuries is undergoing treatment at the hospital and is being provided necessary medical care.

Earlier, an incident involving the rupture of a Cold Separator operating at high pressure in the Coker Hydrotreater Unit resulted in a fire at around noon. The battery limits of the affected unit were immediately isolated, and MRPL's emergency response and firefighting teams were deployed to control the situation.

Further verified information will be shared as and when available.

Issued by

Dr Rudolph V.J. Noronha

Chief General Manager (Corporate Branding and Corporate Communications)

rudolph@mrpl.co.in, 9448495768 0824 2882170