




达妙科技|DAMIAO














It is not recommended to use the M4 threaded hole on the back cover as a connection for load-bearing structural components, as it may cause damage to the back cover structure.







Part Number	
DM-JH20-2EC	
Loan (Pass) Registration	
Tracing	
Proofreading	
Old base map number	
Base map number	
Signature	
Date	
2026/10/23	